



Shop Name: Dekra MFC Auction House  
Tel: --  
Email: --  
Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20250422142501  
Test Time: 2025-04-22 14:25:01  
Technician: Andrick

# Toyota VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Toyota/Hiace/Ventury/--  
VIN: AHTSS22P207123382

Odometer Reading: 276886km  
License Plate: JZ97KBGP

## Customer Information

Name: Dekra MFC AUCTION HOUSE






Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V11.20

Serial Number: VB8GJCC01514  
Repair Order Number: --

## System Scanned( 5 )

System	Status/DTC
Engine and ECT	 0
ABS/VSC/TRC	 2
SRS airbag	 2
Combination meter	 2
Immobilizer	 0

## DTC ( 6 )

### ABS/VSC/TRC ( 2 DTCs )

DTC	Description	Status
C0210	Right rear speed sensor circuit	Current
C1241	Low or high power supply voltage	Current

### SRS airbag ( 2 DTCs )

DTC	Description	Status
B1801	Driving side squib circuit open	History
B1806	P squib circuit open	History

### Combination meter ( 2 DTCs )

DTC	Description	Status
B1507	Turn signal circuit open	History
B1508	Turn signal/hazard flasher circuit short	History

## Technician Notes

2016850657



Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.