

Shop Name: Dekra MFC Auction House

Email: --

Address: MFC AUCTION HOUSE

M57 PRETORIA ROAD **KEMPTON PARK** 

Report ID: MAXIA20250305131849 Test Time: 2025-03-05 13:18:49

Technician: Andrick

# **Toyota VEHICLE DIAGNOSTIC REPORT**

#### **Vehicle Information**

--/Toyota/Hiace/Ventury/--VIN: AHTSS22P607122140

Odometer Reading: 268128km License Plate: JZ00XMGP

**Customer Information** 

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

**Device information** 

Scanner: MaxiSys MS906 BT

Version: V11.20

Serial Number: VB8GJCC01514

Repair Order Number: --

## 🔁 System Scanned( 5 )

| System            | Status/DTC |
|-------------------|------------|
| Engine and ECT    | <b>②</b> 0 |
| ABS/VSC/TRC       | <b>Q</b> 1 |
| SRS airbag        | <b>Q</b> 2 |
| Combination meter | <b>⊘</b> 0 |
| Immobilizer       | <b>②</b> 0 |

## Material Description ■ DTC (3)

DTC

### ABS/VSC/TRC (1 DTC)

Description

| C1241        | Low or high power supply voltage | Current |
|--------------|----------------------------------|---------|
| SRS airbag ( | 2 DTCs)                          |         |
| DTC          | Description                      | Status  |
| B1801        | Driving side squib circuit open  | History |
| B1806        | P squib circuit open             | History |

### **Technician Notes** 2016788421

Customer name: \_ Technician: Date:

**Status** 

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys MS906 BT

Page 1