



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250730133514
Test Time: 2025-07-30 13:35:14
Technician: Werner

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--
VIN: AHTSS22P807143328

Odometer Reading: 277714km
License Plate: 90MMMJL

Customer Information

Name: Dekra MFC AUCTION HOUSE






Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V11.40

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(5)

System	Status/DTC
Engine and ECT	 2
ABS/VSC/TRC	 5
SRS airbag	 3
Combination meter	 1
Immobilizer	 0

DTC (11)

Engine and ECT (2 DTCs)

DTC	Description	Status
P0607	Control module performance	Current
P0607	Control module performance	History

ABS/VSC/TRC (5 DTCs)

DTC	Description	Status
C1201	Engine/EV control system malfunction	History
C1241	Low or high power supply voltage	History
C1402	Fault in front speed sensor left circuit	Current
C1402	Fault in front speed sensor left circuit	History
C1424	Master cylinder pressure sensor zero point output	History

SRS airbag (3 DTCs)

DTC	Description	Status
B1801	Driving side squib circuit open	Current
B1801	Driving side squib circuit open	History
B1806	P squib circuit open	History



Combination meter (1 DTC)

DTC	Description	Status
U0129	Lost communication with brake system control module	History

Technician Notes
2016963016

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.