

# Toyota VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Toyota/Hiace/Ventury/--  
 VIN: AHTSS22PX07109813

Odometer Reading: 375175km  
 License Plate: FHW466L

## Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
 Version: V9.10

Serial Number: VB8GJCC01482  
 Repair Order Number: --

## System Scanned( 6 )

System	Status/DTC
Engine and ECT	0
ABS/VSC/TRC	1
SRS airbag	2
Combination meter	3
Cruise control	0
Immobilizer	0

## DTC ( 6 )

### ABS/VSC/TRC ( 1 DTC )

DTC	Description	Status
C1241	Low or high power supply voltage	Current

### SRS airbag ( 2 DTCs )

DTC	Description	Status
B1801	Driving side squib circuit open	History
B1806	P squib circuit open	History

### Combination meter ( 3 DTCs )

DTC	Description	Status
U0100	Lost communication with ECM/PCM/EV "A"	History
U0129	Lost communication with brake system control module	History
B1507	Turn signal circuit open	History

## Technician Notes

2016205372

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.