

Mitsubishi VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Mitsubishi/ASX/--

VIN: JMYXTGA2WFZ002379

Odometer Reading: 176655

License Plate: HPY327EC

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information


















Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01482

Version: V8.90

Repair Order Number: --

System Scanned (15)

System	Status/DTC
MPI/GDI/Diesel	 0
AT/CVT/A-MT/TC-SST	 0
ABS/ASC/ASTC/WSS - A.S.C.	 0
SRS-Air Bag	 2
Meter	 0
Air Conditioner	 0
AUTO CRUISE 	 0
4WS/Electric Power Steering	 0
Steering Angle Sensor	 0
KOS/IMMO/Keyless/TPMS - IMMOBI & KOS	 2
AFS/ACL/Leveling 	 0
OSS	 0
CORNER SENSOR/BACK SENSOR	 0
ETACS - Selection 102	 0
LIN - Selection 102	 1

DTC (5)

SRS-Air Bag (2 DTCs)

DTC	Description	Status
-----	-------------	--------

B1477	IG1(B) voltage extraordinary low	Stored DTC
B1476	IG1(A) voltage extraordinary low	Stored DTC

KOS/IMMO/Keyless/TPMS - IMMOBI & KOS (2 DTCs)

DTC	Description	Status
B1A11	Keyless/KOS key 2 low battery	Active DTC
B1A10	Keyless/KOS key 1 low battery	Active DTC

LIN - Selection 102 (1 DTC)

DTC	Description	Status
L0432	RLS RS adaptation error	Stored DTC

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.