

Infiniti VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Infiniti/Infiniti Q50/--

VIN: JN1BDAV37U0203583

Odometer Reading: 191152.00km

License Plate: DP04PCGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information





















Scanner: MaxiSys MS906 BT

Version: V9.50

Serial Number: VB8GJCC01509

Repair Order Number: --

System Scanned(20)

System	Status/DTC
Engine	 8
Transmission	 1
ABS	 4
Air bag	 1
Meter/M&A	 0
Electric Power Steering (EPS)/DAST 3	 0
Air pressure monitor	 1
BCM	 7
ICC/ADAS	  1
HVAC	 1
Multi AV	 3
IPDM E/R	 1
Sonar	 1
CAN gateway	 0
Pop up hood	 0
ANC	 1
EMCM	 1
Chassis control	  2

FSCM ✔ 0Headlamp levelizer ✔ 0

ADAS

 **DTC (33)****Engine (8 DTCs)**

DTC	Description	Status
P244B:00	Particulate filter DIFF press [no subtype information]	Current
P2600:13	Coolant pump A (Open circuit)	Current
P2280:07	Air flow restriction/air leakage (Mechanical fault)	Current
P2454:14	Particulate filter press SEN a (Open circuit or short circuit to ground)	Current
P244A:00	Particulate filter differential pressure [no subtype information]	Past
P244A:7A	Particulate filter differential pressure (Fluid leakage or seal fault)	Past
P2463:09	PF restriction b1 (Component fault)	Past
P2453:28	Particulate filter pressure sensor A (Signal BS level out of range/zero adjustment flr)	Past

Transmission (1 DTC)

DTC	Description	Status
U0121	Communication error (lost)	Current

ABS (4 DTCs)

DTC	Description	Status
C1116	Stop lamp switch	Past
C1140	Actuator rly	Past
U1000	CAN communication circuit	Past
C1155	BR fluid level low	Past

Air bag (1 DTC)

DTC	Description	Status
B142A:16	Ignition voltage (Low)	Past

Air pressure monitor (1 DTC)

DTC	Description	Status
C1704	Low pressure (left front)	Past

BCM (7 DTCs)

DTC	Description	Status
-----	-------------	--------

B2014	Steering lock - BCM chain	Past
B2562	Low voltage	Past
B261A	Push button ignition switch	Past
B25A0	LIN communication error PWD main switch	Past
B25A1	LIN communication error driver PWD actuator	Past
B25A2	LIN communication error assist PWD actuator	Past
B25A3	LIN communication error rear PWD actuator	Past

ICC/ADAS (1 DTC)

DTC	Description	Status
U1000	CAN COMM circuit	Past

HVAC (1 DTC)

DTC	Description	Status
U1000	CAN communication circuit	

Multi AV (3 DTCs)

DTC	Description	Status
U1300	AV communication circuit	Past
U1249	Audio head unit connection	Past
U1267	Meter CONN	Past

IPDM E/R (1 DTC)

DTC	Description	Status
U1000	CAN communication circuit	Past

Sonar (1 DTC)

DTC	Description	Status
U1000	CAN communication circuit	Past

ANC (1 DTC)

DTC	Description	Status
B1F07	CAN signal error/mode switching	Past

EMCM (1 DTC)

DTC	Description	Status
P1656	Engine restart bypass relay	Current

Chassis control (2 DTCs)

DTC	Description	Status
U1000:00	CAN COMM circuit	Past

U1A48:00 ECM/HPCM communication

Past

Technician Notes

2016292285

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.