

Shop Name: --Tel: --Email: --Address: --

Report ID: MAXIA20250726084736 Test Time: 2025-07-26 08:47:36

Technician: Travino

Toyota VEHICLE DIAGNOSTIC REPORT

			•			
Ve	hic	ile I	nto	rm	atio	n

--/Toyota/Rumion/--VIN: JTDDND22S00454269 Odometer Reading: 129040 License Plate: HFF624L

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

System Scanned(7)

Repair Order Number: --

Serial Number: VB8GJCC01509

Version: V4.71

System	Status/DTC
Engine/powertrain	② 0
ABS/ESP	Q 1
Airbag	② 0
Instrument Panel Cluster (IPC)/meter/M&A	② 0
Power steering	② 0
BCM	② 0
Immobilizer and/or keyless system	② 0



ABS/ESP (1 DTC)

DTC	Description	Status
C1057	Power supply voltage	History

Technician Notes 2016959141

Customer name: __ Technician: ___ Date: __

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys MS906 BT

Page 1