



Shop Name: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20260911123751
Test Time: 2026-09-11 12:37:51
Technician: Sbu

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Urban Cruiser/--
VIN: JTDUYMJ1S00105669

Odometer Reading: 37909
License Plate: CAA145-909

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (5)

System	Status/DTC
ECM/PCM(Engine/powertrain)	 0
TCM(Transmission Control Module)	 0
SRS(Airbag)	 0
CGW(Central gateway control module)	 1
EPS(Power steering)	 0

DTC (1)

CGW(Central gateway control module) (1 DTC)

DTC	Description	Status
U0121-87	Lost communication with ABS or electronic stability program control module	History

Technician Notes

2017297770

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

