

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--
VIN: JTFPA9AP208022697

Odometer Reading: 185660km
License Plate: KH00WFGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V11.30

Serial Number: VB8GJCC01509
Repair Order Number: --

 System Scanned(13)

System	Status/DTC
Engine	 0
SRS airbag	 0
Combination meter	 1
Brake	 1
Main body	 4
Driver door motor	 0
Passenger door motor	 2
Air conditioner	 0
Cruise control	  0
Steering angle sensor (SAS)	 0
Central gateway	 0
Master switch	 0
Immobilizer	 0

 DTC (8)

Combination meter (1 DTC)

DTC	Description	Status
U012987	Lost communication with brake system control module missing message	Confirmed

Brake (1 DTC)

DTC	Description	Status
C137BA2	Brake system control module "A" system voltage system voltage low	Confirmed

Main body (4 DTCs)

DTC	Description	Status
B2321	Driver door motor ECU communication stop	History
B1206	P/W master switch ECU communication stop	History
U0129	Lost communication with brake system control module	History
U0163	Lost communication with navigation control module	History

Passenger door motor (2 DTCs)

DTC	Description	Status
B2313	Glass position initialization incomplete	Current
B2312	Power window switch of passenger door fault	History

Technician Notes

2016950947

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.