



Shop: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20240812102922
Test Time: 2024-08-12 10:29:22
Technician: Sbu

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Accent(RB)/--
VIN: KMHCU41DMHU135734

Odometer Reading: 268548
License Plate: FH64YBGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.80

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(8)

System	Status/DTC
ENG (Engine)	 3
A/T (Transaxle)	 5
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 1
AB (Airbag)	 0
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 1
BCM (Body Control)	 0

DTC (10)

ENG (Engine) (3 DTCs)

DTC	Description	Status
P0268	Cylinder 3 injector circuit high	History
P0616	Starter relay circuit low	History
P2188	System too rich at idle (Bank 1)	History

A/T (Transaxle) (5 DTCs)

DTC	Description	Status
P0743	Torque converter clutch (TCC) circuit electrical fault	History
P0750	Shift control solenoid valve A (on/Off)	History
P0755	Shift control solenoid valve B (PCSV-A)	History



P0760	Shift control solenoid valve C (PCSV-B)	History
P0765	Shift control solenoid valve D (PCSV-C)	History

ABS/ESP (Anti Lock Brake/Electronic Stability Program) (1 DTC)

DTC	Description	Status
C1211	Right rear vehicle speed sensor (VSS) invalid/No signal	History

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1611	CAN Timeout - Engine management system (EMS)	History

Technician Notes

2016488229

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.