



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250527163149
Test Time: 2025-05-27 16:31:49
Technician: Travino

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Tucson(TL)/--
VIN: KMHJ2813LHU286662

Odometer Reading: 281641
License Plate: LH88LXGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.87

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(9)

System	Status/DTC
ENG (Engine)	 1
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 1
CLU (Cluster Module)	 0
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0
BCM (Body Control)	 0
SJB (Smart Junction Block)	 0

DTC (2)

ENG (Engine) (1 DTC)

DTC	Description	Status
P0014	Exhaust camshaft position (CMP) B timing over-Advanced or system performance (Bank 1)	History

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

Technician Notes

2016892799



Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.