



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250522143228
Test Time: 2025-05-22 14:32:28
Technician: Sbu

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Tucson(TL)/--
VIN: KMHJ3813MHU285241

Odometer Reading: 78502
License Plate: FR18PGGP

Customer Information

Name: Dekra MFC AUCTION HOUSE
















Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.87

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(13)

System		Status/DTC
ENG (Engine)		 0
A/T (Transaxle)		 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)		 0
AB (Airbag)		 0
CLU (Cluster Module)		 0
CODE (Transmitter Code Saving)		 0
A/C (Air Conditioner)		 0
EPS (Motor Driven Power Steering)		 0
BCM (Body Control)		 0
SMK (Smart Key Unit)		 0
SJB (Smart Junction Block)		 0
BSD-L (Blind Spot Detection-L)		 0
BSD-R (Blind Spot Detection-R)		 0

DTC (0)

Technician Notes

2016887195



Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.