

Shop Name: Dekra MFC Auction House

Tel: --

Email: --

Address: MFC AUCTION HOUSE

M57 PRETORIA ROAD **KEMPTON PARK**

Report ID: MAXIA20250402112748 Test Time: 2025-04-02 11:27:48

Technician: Sbu

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Pride(UB)/--VIN: KNADN512LF6564235 Odometer Reading: 182026 License Plate: DX25XNGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

🔀 System Scanned(7)

Serial Number: VB8GJCC01514

Repair Order Number: --

Version: V13.86

System	Status/DTC
ENG (Engine)	Q 2
ABS/VDC (Anti Lock Brake system/Vehicle Dynamic Control)	② 0
AB (Airbag)	Q 1
EPS (Motor Driven Power Steering)	Q 1
BCM (Body Control)	② 0
CODE (Transmitter Code Saving)	② 0
IMMO (Immobilizer)	② 0

Material Description ■ DTC (4)

ENG (Engine) (2 DTCs)

AD (Airbar) (1 DTO)		
U1112	LIN Communication error	Active
P2188	System too rich at idle (Bank 1)	History
DTC	Description	Status

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1611	CAN Timeout - Engine management system (EMS)	History

Technician Notes

2016825494



MaxiSys MS906 BT

/Kia/Pride(UB)	Test Time: 2025	5-04-02 11:27:48 Report ID: N	MAXIA20250402112748

Customer name: _	
Technician: _	
Data	
Date: _	

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys MS906 BT Page 2

Note:Please save a copy of this report for your records.