



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250416135551
Test Time: 2025-04-16 13:55:51
Technician: Travino

GreatWall VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/GreatWall/Wingle 5/2021/--
VIN: LGWCBE374NB670649
Odometer Reading: 46235
License Plate: LD94FCGP

Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V11.00
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(6)

System	Status/DTC
ECM (Engine Control Module)-4D20D Bosch China 5 diagnostic system	5
SRS (Supplemental Restraint System)-SRS (Supplemental Restraint System)	1
BCM (Body Control Module)	1
ICM/IP (Instrument Cluster Module/Instrument Pannel)	1
ABS/ESP (Anti-lock Braking System/Electronic Stability Program)-ESP (Electronic Stability Program)	0
IMMO (Immobilizer)-Delphi gasoline immobilizer system	0

DTC (8)

ECM (Engine Control Module)-4D20D Bosch China 5 diagnostic system (5 DTCs)

DTC	Description	Status
P056216	Battery voltage too low and leads to relevant components stop working	History DTC
U110116	INM low voltage	History DTC
P063300	Immobilizer (immo) response invalid	History DTC
P226409	Oil water separator sensor self-test malfunction (sensor damaged)	History DTC
P068A00	Main relay, premature disconnect fault	History DTC

SRS (Supplemental Restraint System)-SRS (Supplemental Restraint System) (1 DTC)

DTC	Description	Status
-----	-------------	--------



908600	Under-voltage	History DTC
--------	---------------	-------------

BCM (Body Control Module) (1 DTC)

DTC	Description	Status
B102313	Rear fog lamp circuit open	Current DTC

ICM/IP (Instrument Cluster Module/Instrument Pannel) (1 DTC)

DTC	Description	Status
U010087	Communication with ECM failed	History DTC

Technician Notes
2016846222

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.