AUTEL

Shop: DEKRA MFC

Tel: --Email: --

Address: MFC Auction House

Kempton Park

Report ID: MAXIA20231222114507 Test Time: 2023-12-22 11:45:07

Technician: Sbu

## **GreatWall VEHICLE DIAGNOSTIC REPORT**

**Vehicle Information** 

---/GreatWall/Haval First Love/--VIN: LGWEE4A58PK607875

**Customer Information** 

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

**Device information** 

Scanner: MaxiSys MS906 BT

Version: V8.60

Odometer Reading: 10719 License Plate: KWV070MP

Tel: 0861033572

Serial Number: VB8GJCC01482

Repair Order Number: --

## 🔁 System Scanned( 17 )

System	Status/DTC
ECM (Engine System)-ECM (Engine System (UMC - 4G15H&4G15K))	<b>②</b> 0
AT (AT System)-TCU (Transmission Control Unit 7DCT - 450)	<b>②</b> 0
ESP (Electronic Stability Program)	<b>Q</b> 1
SRS (Airbag System)	<b>Q</b> 1
BCM (Body Control Module)-KBCM (KSD body electronic domain control unit)	<b>②</b> 0
ICM/IP (Instrument cluster system)-IP (IP System, 3.5 Inch)	<b>②</b> 0
TPMS (Tire Pressure Monitoring System)	<b>Q</b> 1
GW (Gateway)	<b>②</b> 0
A/C (automatic air conditioning system)	<b>Q</b> 6
APS (Automatic Parking System)	<b>Q</b> 3
CSA (group with switch assembly)	<b>②</b> 0
EPS (Electric Power Steering )-EPS (Bosch Electronic Power Steering System)	<b>Q</b> 2
F-PBOX (Front Fuse Box Module)	<b>②</b> 0
R-PBOX (Rear Fuse Box Module)	<b>②</b> 0
HUT (Navigation System)	<b>Q</b> 27

MaxiSys MS906 BT

Page 1

Page 2

GreatWall/ Hava	Il First Love/ Test Time: 2023-12-22 11:45:07	Report ID: MAXIA20231222114507
B12BE87	Left camera lost	Current DTC
B12BF87	Right camera lost	Current DTC
U110017	Communication voltage too high	History DTC
U110116	Communication voltage too low	History DTC
U007388	CAN busoff	History DTC
B1A0101	Left front speaker circuit short	History DTC
B1A0111	Left front speaker circuit short to ground	History DTC
B1A0112	Left front speaker circuit short to power	History DTC
B1A0125	Please refer to vehicle service manual.	History DTC
B1A0201	Right front speaker circuit short	History DTC
B1A0211	Right front speaker circuit short to ground	History DTC
B1A0212	Right front speaker circuit short to power	History DTC
B1A0225	Please refer to vehicle service manual.	History DTC
B1A0301	Left rear speaker circuit short	History DTC
B1A0311	Left rear speaker circuit short to ground	History DTC
B1A0312	Left rear speaker circuit short to power	History DTC
B1A0325	Please refer to vehicle service manual.	History DTC
B1A0401	Right rear speaker circuit short	History DTC
B1A0411	Right rear speaker circuit short to ground	History DTC
B1A0412	Right rear speaker circuit short to power	History DTC
B1A0425	Please refer to vehicle service manual.	History DTC
B108E87	Lost communication with HD display	History DTC
B12BC87	Front camera lost	History DTC
B12BE87	Left camera lost	History DTC
B12BF87	Right camera lost	History DTC
B210613	FM/AM antenna circuit open	History DTC
RPAS (Parking	g Assistant System - rear) ( 3 DTCs )	
DTC	Description	Status
U024587	Lost communication with HUT	History DTC
U012286	Electronic stability program checksum error	History DTC
U110116	ECU voltage too low	History DTC

AUTEL www.autel.com MaxiSys MS906 BT Page 3

GreatWall/ Haval First Love/	Test Time	2023-12-22 11:45:07	Report ID:	MAXIA20231222114507
Gleatwall, Havai Hist Love,	Test Hille.	2023-12-22 11.43.01	neport ib.	IVIANIAZUZUTZZZTT4JUT

## **Technician Notes**

2016210404

Customer name:	
Technician:	
Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

AUTEL www.autel.com

MaxiSys MS906 BT Page 4