



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20240112122041
Test Time: 2024-01-12 12:20:41
Technician: Sbu

GreatWall VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/GreatWall/Great Wall C50/2016(sports model)/--
VIN: LGWEF3K59EF620811

Odometer Reading: 225894
License Plate: FB19RHGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V8.60

Serial Number: VB8GJCC01482
Repair Order Number: --

System Scanned(6)

System	Status/DTC
ECM (Engine System)	 6
ESP (Electronic Stability Program)-Anti-lock brake system	 3
SRS (Airbag System)	 2
BCM (Body Control Module)	 0
ICM/IP (Instrument cluster system)	 0
IMMO (Immobilizer)	 0

DTC (11)

ECM (Engine System) (6 DTCs)

DTC	Description	Status
P0571	Brake Switch 'A' Circuit	
P0300	Random/Multiple Cylinder Misfire Detected	
P0301	Cylinder 1 Misfire Detected	
P0302	Cylinder 2 misfire detected	
P0342	Camshaft position sensor signal low	
P0560	System Voltage Malfunction	

ESP (Electronic Stability Program)-Anti-lock brake system (3 DTCs)

DTC	Description	Status
C0031	Left front speed sensor	Current DTC
C1001	Kl. 30 board voltage	History DTC
C0031	Left front speed sensor	History DTC



SRS (Airbag System) (2 DTCs)

DTC	Description	Status
B200100	Battery low voltage fault	History DTC
B10A100	Impact output signal short to ground or open circuit	History DTC

Technician Notes

2016226947

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.