

HAVAL VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/HAVAL/Haval H6/China/H6S (hybrid edition)/--
VIN: LGWFF6A56PH928159

Odometer Reading: 86333
License Plate: LC22CCGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.00

Serial Number: VB8GJCC01509
Repair Order Number: --



System Scanned (26)

System	Status/DTC
ECM (Engine Control Module)	✓ 0
ESP (Electronic Stability Program)	✓ 0
SRS (Supplemental Restraint System)	✓ 0
BCM (Body Control Module)-BCM (Body Control Module) - KOSTAL	✗ 2
TPMS (Tire Pressure Monitoring System)	✗ 2
A/C (Air Conditioning) -A/C (Air Conditioning) - MIND	✗ 1
IPAS (Integrated Parking Assist System)	ADAS ✗ 1
CSA (Combination Switch Assembly) - with Steering Angle Sensor Calibration Function	✓ 0
DDCM (Driver Door Control Module)	✗ 2
EPS (Electric Power Steering)-EPS (Electric Power Steering) - ZF	✗ 1
F-PBOX (Front Fuse Box Module)	✗ 1
GW (Gateway)-GW (Gateway) - Aptiv	✓ 0
HAP (High-level Automatic Parking)	ADAS ✗ 1
HUD (Head-Up Display)-HUD (Head-Up Display) - E-lead	ADAS ✓ 0
HUT (Multimedia Player Assembly)	ADAS ✗ 1
SHM (Seat Heating Module)-HVSM (Heating and Ventilation Seat Module) - Gentherm	✓ 0
IFC (Intelligent Front Camera)	ADAS ✗ 2

PAS (Parking Assist System)	ADAS	 1
PDCM (Passenger Door Control Module)		 2
PLG (Power Liftgate)		 0
R-PBOX (Rear Fuse Box Module)		 1
RSDS-L (Radar Sensing and Detection System - Left)	ADAS	 3
RSDS-R (Radar Sensing and Detection System - Right)	ADAS	 3
SBWM (Shift-By-Wire Module)-SBWM (Shift-By-Wire Module) - MIND		 0
T-Box (Telematics Box)-T-Box (Telematics Box) - Lear		 0
WPC (Wireless Power Charging)		 1

 DTC (25)**BCM (Body Control Module)-BCM (Body Control Module) - KOSTAL (2 DTCs)**

DTC	Description	Status
B185100	Key battery low	Current DTC
U014400	Sunroof monitoring fault	History DTC

TPMS (Tire Pressure Monitoring System) (2 DTCs)

DTC	Description	Status
C007704	Left rear tire low pressure warning	Current DTC
U016387	Lost communication with HUT (navigation host system)	History DTC

A/C (Air Conditioning) -A/C (Air Conditioning) - MIND (1 DTC)

DTC	Description	Status
U024587	Lost communication with navigation host system	History DTC

IPAS (Integrated Parking Assist System) (1 DTC)

DTC	Description	Status
U100087	Lost communication with Air Bag Module (ABM)	History DTC

DDCM (Driver Door Control Module) (2 DTCs)

DTC	Description	Status
U010187	Lost communication with Transmission Control Unit (TCU)_PTCAN	History DTC
U012287	Lost communication with ESP(ABS)	History DTC

EPS (Electric Power Steering)-EPS (Electric Power Steering) - ZF (1 DTC)

DTC	Description	Status
U000123	SFS failure - 2	History DTC

F-PBOX (Front Fuse Box Module) (1 DTC)

DTC	Description	Status
U024587	Lost communication with navigation host system (HUT)	History DTC

HAP (High-level Automatic Parking) (1 DTC)

DTC	Description	Status
U100087	Lost communication with Air Bag Module (ABM)	History DTC

HUT (Multimedia Player Assembly) (1 DTC)

DTC	Description	Status
B210149	Instrument panel display IC failure	History DTC

IFC (Intelligent Front Camera) (2 DTCs)

DTC	Description	Status
C153700	Windshild blurred	History DTC
C153600	Ambient interference	History DTC

PAS (Parking Assist System) (1 DTC)

DTC	Description	Status
U100087	Lost communication with Air Bag Module ABM	History DTC

PDCM (Passenger Door Control Module) (2 DTCs)

DTC	Description	Status
U010187	Lost communication with Transmission Control Unit (TCU)_PTCAN	History DTC
U012287	Lost communication with ESP(ABS)	History DTC

R-PBOX (Rear Fuse Box Module) (1 DTC)

DTC	Description	Status
U024587	Lost communication with navigation host system (HUT)	History DTC

RSDS-L (Radar Sensing and Detection System - Left) (3 DTCs)

DTC	Description	Status
U014087	Lost communication with KBCM	History DTC
U019987	Lost communication with driver door control module	History DTC
U020087	Lost communication with passenger door control module	History DTC

RSDS-R (Radar Sensing and Detection System - Right) (3 DTCs)

DTC	Description	Status
U014087	Lost communication with KBCM	History DTC
U019987	Lost communication with driver door control module	History DTC
U020087	Lost communication with passenger door control module	History DTC

WPC (Wireless Power Charging) (1 DTC)

DTC	Description	Status
-----	-------------	--------

U010087

Lost communication with ECM

History DTC

Technician Notes

2017298420

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.