

Maruti Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Maruti Suzuki/Swift/--

VIN: MA3GZF62S00480504

Odometer Reading: 84222

License Plate: DT43XWGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Version: V4.40

Serial Number: VB8GJCC01482

Repair Order Number: --

System Scanned (7)

System	Status/DTC
Engine/powertrain	0
ABS/ESP	1
Airbag	1
Instrument Panel Cluster (IPC)/meter/M&A	0
Power steering	1
BCM	0
Immobilizer and/or keyless system	0

DTC (3)

ABS/ESP (1 DTC)

DTC	Description	Status
C1033	Wheel Speed Sensor (WSS) deviation	History

Airbag (1 DTC)

DTC	Description	Status
B1017	Power source voltage too low	History

Power steering (1 DTC)

DTC	Description	Status
C1153	Power supply voltage too low or too high	History

Technician Notes

2016097515

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.