

# Maruti Suzuki VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Maruti Suzuki/S-presso/--  
 VIN: MA3RFL41S00165166

Odometer Reading: 63038  
 License Plate: JN63MWGP

## Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
 Version: V4.51

Serial Number: VB8GJCC01482  
 Repair Order Number: --

## System Scanned( 7 )

System	Status/DTC
Engine/powertrain	0
ABS/ESP	2
Airbag	0
Instrument Panel Cluster (IPC)/meter/M&A	0
Power steering	0
BCM	3
Immobilizer and/or keyless system	3

## DTC ( 8 )

### ABS/ESP ( 2 DTCs )

DTC	Description	Status
C1057	Power supply voltage	History
C1061	Pump motor circuit performance	History

### BCM ( 3 DTCs )

DTC	Description	Status
B1133	Battery voltage too high	History
B1157	Airbag impact signal input	History
B1189	Immobilizer antenna communication fault	History

### Immobilizer and/or keyless system ( 3 DTCs )

DTC	Description	Status
B1133	Battery voltage too high	History

B1157	Airbag impact signal input	History
B1189	Immobilizer antenna communication fault	History

**Technician Notes**

2016230902

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.