



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250409144203
Test Time: 2025-04-09 14:42:03
Technician: Andrick

Ford VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Ford/FIGO/--
VIN: MAJ1XXMRJ1BC02552

Odometer Reading: 338171km
License Plate: BG43TWGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V8.80

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(4)

System	Status/DTC
PCM(Powertrain control module)	 9
ABS(Anti-lock brake system/traction control module)	 4
RCM(Restraint control module)	 3
IC(Instrument cluster)	 3

DTC (19)

PCM(Powertrain control module) (9 DTCs)

DTC	Description	Status
P0460:60	Fuel Level Sensor A Circuit	CMDTCs
P0500:60	VSS(Vehicle speed sensor) sensor circuit fault.	CMDTCs
P061D:60	Internal Control Module Engine Air Mass Performance	CMDTCs
P1632:60	Smart Alternator Faults Sensor / Circuit	CMDTCs
P1794:60	Battery voltage	CMDTCs
P2176:E0	Throttle Actuator Control System - Idle Position Not Learned	CMDTCs
B1601:60	PATS(Passive Anti Theft System) received incorrect key-code from ignition transponder.	CMDTCs
U0121:60	Lost Communication With The ABS(Antilock braking system) Control Module	CMDTCs
U0155:60	Lost Communication With The Instrument Panel Cluster Control Module	CMDTCs

ABS(Anti-lock brake system/traction control module) (4 DTCs)

DTC	Description	Status
C1143	Left Rear Tone Ring Missing Tooth Fault	CMDTCs



C1236	The left rear wheel speed sensor input signal missing or the signal is not plausible.	CMDTCs
B1317	Battery voltage too high	CMDTCs
B1318	Battery Voltage Low	CMDTCs

RCM(Restraint control module) (3 DTCs)

DTC	Description	Status
B1318	Battery Voltage Low	CMDTCs
B1868	Lamp Air Bag Warning Indicator circuit failure	CMDTCs
U0155	Lost Communication With The Instrument Panel Cluster Control Module	CMDTCs

IC(Instrument cluster) (3 DTCs)

DTC	Description	Status
B2895:60	Trip Computer Mode Switch Circuit Failure	CMDTCs
U0074:20	Bluetooth Communication Failure to Phone	CMDTCs
U0151:60	Missing CAN(Controller Area Network) Message From RCM(Restraint Control Module)	CMDTCs

Technician Notes
2016835778

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.