

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Grand i10/Xcent (BA)/--
 VIN: MALA851CLGM388073

Odometer Reading: 170207
 License Plate: FG67RCGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE







Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
 Version: V13.50

Serial Number: VB8GJCC01482
 Repair Order Number: --

System Scanned(6)

System	Status/DTC
ENG (Engine)	 5
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 1
AB (Airbag)	 2
CLU (Cluster Module)	 0
IMMO (Immobilizer)	 0
EPS (Motor Driven Power Steering)	 4

DTC (12)

ENG (Engine) (5 DTCs)

DTC	Description	Status
P0011	Intake camshaft position (CMP) A timing over-Advanced or system performance (Bank 1)	History
P0014	Exhaust camshaft position (CMP) B timing over-Advanced or system performance (Bank 1)	Active
P0134	Oxygen sensor circuit no activity detected (Bank 1 sensor 1)	Pending
P0202	Cylinder 2 injector circuit/open	Active
P0501	Vehicle speed sensor (VSS) A circuit range/performance	Active

ABS/ESP (Anti Lock Brake/Electronic Stability Program) (1 DTC)

DTC	Description	Status
C1102	Battery voltage low	History

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B2500:00	Warning lamp failure	Active

EPS (Motor Driven Power Steering) (4 DTCs)

DTC	Description	Status
C1109	Ignition open	History
C1604	ECU hardware Error	History
C1611	CAN Timeout - Engine management system (EMS)	History
C1622	Engine management system (EMS) vehicle speed invalid	Active

Technician Notes

2016228985

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.