

Shop Name: Dekra MFC Auction House

Tel: --Email: --Address: MFC AUCTION HOUSE M57 PRETORIA ROAD KEMPTON PARK Report ID: MAXIA20250730152845 Test Time: 2025-07-30 15:28:45

Technician: Sbu

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/i20(PB)/--VIN: MALBB51CLBM285653 Odometer Reading: 246704 License Plate: BT89BSGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01514

Repair Order Number: --

Version: V13.90

🔀 System Scanned(7)

System	Status/DTC
ENG (Engine)	Q 2
ESP (Electronic Stability Program)	Q 8
AB (Airbag)	Q 4
IMMO (Immobilizer)	② 0
CODE (Transmitter Code Saving)	② 0
EPS (Motor Driven Power Steering)	Q 1
BCM (Body Control)	② 0

TOTE (15)

ENG (Engine) (2 DTCs)

DTC	Description	Status
P0012	Intake camshaft position (CMP) A timing over-Retarded (Bank 1)	Active
P0118	Engine coolant temperature (ECT) circuit input high	Active
ESP (Electronic Stability Program) (8 DTCs)		
DTC	Description	Status

DTC	Description	Status
C1101	Battery voltage high	History
C1102	Battery voltage low	History
C1202	Left front vehicle speed sensor (VSS) invalid/No signal	History
C1203	Right front vehicle speed sensor (VSS) circuit open or short	Active
C1204	Right front vehicle speed sensor (VSS) range/performance/Intermittent	History



n MaxiSys MS906 BT Page 1

/Hyundai/i20(PB)	Test Time: 2025-07-30 15:28:45	Report ID: MAXIA20250730152845
C1205	Right front vehicle speed sensor (VSS) invalid/No signal	History
C1207	Left rear wheel speed sensor (WSS) range/performance/Intermittent	History
C1210	Right rear vehicle speed sensor (VSS) range/performance/Intermittent	History
AB (Airbag) (4 DTCs)		

DTC	Description	Status
B1101	Battery voltage high	Active
B1102	Battery voltage low	Active
B1346	Driver airbag (DAB) resistance too high (1st Stage)	Active
B2500	Warning lamp failure	Active

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1617	Engine management system (EMS) engine speed invalid	History

Technician Notes 2016962855

Customer name: _	
Technician: _	
Date: _	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



ww.autel.com MaxiSys MS906 BT