



Shop Name: Dekra MFC Auction House

Tel: --

Email: --

Address: MFC AUCTION HOUSE

M57 PRETORIA ROAD

KEMPTON PARK

Report ID: MAXIA20250331115430

Test Time: 2025-03-31 11:54:30

Technician: Sbu

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/i20(PB)/--

VIN: MALBB51CLDM554451

Odometer Reading: 97134

License Plate: CZ41XJGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Version: V13.86

Serial Number: VB8GJCC01514

Repair Order Number: --

System Scanned(7)

System	Status/DTC
ENG (Engine)	 0
ESP (Electronic Stability Program)	 0
AB (Airbag)	 1
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
A/C (Air Conditioner)	 0
EPS (Motor Driven Power Steering)	 0

DTC (1)

AB (Airbag) (1 DTC)

DTC	Description	Status
B1346	Driver airbag (DAB) resistance too high (1st Stage)	Active

Technician Notes

2016821942

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

