



Shop Name: Dekra MFC Auction House  
Tel: --  
Email: --  
Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20250523110419  
Test Time: 2025-05-23 11:04:19  
Technician: Travino

# Toyota VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Toyota/Etios/--  
VIN: MBBJ29BT200129834

Odometer Reading: 177980  
License Plate: KK83TWGP

## Customer Information

Name: Dekra MFC AUCTION HOUSE







Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V11.30

Serial Number: VB8GJCC01514  
Repair Order Number: --

## System Scanned( 5 )

System	Status/DTC
Engine and ECT	 0
ABS/VSC/TRC	 4
Cruise control	  0
Immobilizer	 0
EMPS	 0

## DTC ( 4 )

### ABS/VSC/TRC ( 4 DTCs )

DTC	Description	Status
C1241	Low or high power supply voltage	History
C1300	Skid control ECU fault	Current
C1300	Skid control ECU fault	History
C1466	Right rear speed sensor circuit	History

## Technician Notes

2016888250

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

