Shop: --Tel: --Email: --

Address: --

Report ID: MAXIA20240430130448 Test Time: 2024-04-30 13:04:48

Technician: Sbu

Page 1

# **Toyota VEHICLE DIAGNOSTIC REPORT**

#### **Vehicle Information**

--/Toyota/Etios/--VIN: MBJB29BTX00121092 Odometer Reading: 202532 License Plate: KN79XCGP

**Customer Information** 

Name: MFC Dekra Nedbank Auction House

**Device information** 

Scanner: MaxiSys MS906 BT

Version: V9.21

Tel: 0861033572

Serial Number: VB8GJCC01509

Repair Order Number: --

### 🔁 System Scanned( 6 )

| System         | Status/DTC |
|----------------|------------|
| Engine and ECT | <b>②</b> 2 |
| ABS/VSC/TRC    | <b>Q</b> 1 |
| SRS airbag     | <b>◎</b> 0 |
| Immobilizer    | <b>◎</b> 0 |
| EMPS           | <b>◎</b> 0 |
| Cruise control | A®AS       |

## ▲ DTC (3)

#### Engine and ECT (2 DTCs)

| DTC                 | Description        | Status  |
|---------------------|--------------------|---------|
| P1604               | Startability fault | Current |
| P1604               | Startability fault | History |
| ABS/VSC/TRC (1 DTC) |                    |         |

| DTC   | Description                      | Status  |
|-------|----------------------------------|---------|
| C1241 | Low or high power supply voltage | History |

www.autel.com MaxiSys MS906 BT

| Toyota/ Etios/ | Test Time: | 2024-04-30 13:04:48 | Report ID: | MAXIA20240430130448 |
|----------------|------------|---------------------|------------|---------------------|

### **Technician Notes**

2016360916

| Customer name: |  |
|----------------|--|
| Technician:    |  |
| Date:          |  |

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys MS906 BT Page 2