

Shop Name: Dekra MFC Auction House Tel: --Email: --Address: MFC AUCTION HOUSE M57 PRETORIA ROAD KEMPTON PARK Report ID: MAXIA20250227160510 Test Time: 2025-02-27 16:05:10 Technician: Werner

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Etios/--VIN: MBJM29BT202014633

Customer Information

Name: Dekra MFC AUCTION HOUSE

Device information

Scanner: MaxiSys MS906 BT Version: V11.20 Odometer Reading: 271458 License Plate: NP209-682

Tel: 0861033572

Serial Number: VB8GJCC01514 Repair Order Number: --

🔁 System Scanned(5)

System		Status/DTC
Engine and ECT		O
ABS/VSC/TRC		3
Cruise control	AØAS	O
Immobilizer		O
EMPS		O

🔼 DTC (7)

ABS/VSC/TRC (7 DTCs)

DTC	Description	Status
C0200	Right front speed sensor circuit	Current
C0205	Left front speed sensor circuit	Current
C0210	Right rear speed sensor circuit	Current
C0215	Left rear speed sensor circuit	Current
C1241	Low or high power supply voltage	Current
C1330	Right front speed sensor circuit open	Current
C1331	Left front speed sensor circuit open	Current

Technician Notes 2016780329



Customer name: _	
Technician: _	
Date: _	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.