

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/TRIBER/--
VIN: MEERBC00500072377

Odometer Reading: 148427
License Plate: LB77HTGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned(7)

System	Status/DTC
Injection	 3
ABS	 2
Airbag / pretensioners	 0
Instrument panel	 1
UCH	 0
Variable PAS	 1
Radio	  3

DTC (10)

Injection (3 DTCs)

DTC	Description	Status
DTC01061C	Inlet pressure consistency Abnormal voltage.	Memory
DTC065711	Main relay control circuit Short circuit to earth.	Memory
DTC250479	Battery voltage 12 V Mechanical failures	Memory

ABS (2 DTCs)

DTC	Description	Status
DTC512764	Wheel speed coherence Signal plausibility failure	Memory
DTCC10000	Injection multiplexed emission missing No communication	Memory

Instrument panel (1 DTC)

DTC	Description	Status
DTC94037B	Brake fluid level circuit Below the min level	Memory

Variable PAS (1 DTC)

DTC	Description	Status
DTC560849	Computer Internal electronic failure	Memory

Radio (3 DTCs)

DTC	Description	Status
DTC932813	Microphone Open circuit	Memory
DTC934149	Computer configuration Internal electronic fault	Memory
DTC93CF73	Key jammed Internal electronic fault	Memory

Technician Notes

2016958188

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.