

Mitsubishi VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Mitsubishi/XPANDER / XPANDER CROSS/--
VIN: MK2LNNC1WPN002362

Odometer Reading: 32234
License Plate: LL89WJGP

Customer Information

Name: MFC Dekra Nedbank Auction House









Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V9.20

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned(8)

System	Status/DTC
MPI/GDI/Diesel	 2
ABS/ASC/EPB	 2
SRS-Air Bag	 1
Meter	 1
4WS/Electric Power Steering	 2
ETACS	 0
KOS/OSS/IMMO/Keyless	 0
Multi Channel Gateway	 0

DTC (8)

MPI/GDI/Diesel (2 DTCs)

DTC	Description	Status
P0513	Incorrect immobilizer key	Active DTC
P0267	No.3 injector circuit low	Active DTC

ABS/ASC/EPB (2 DTCs)

DTC	Description	Status
C102B	RR wheel speed sensor circuit	Active DTC
C1020	RL wheel speed sensor circuit	Active DTC

SRS-Air Bag (1 DTC)

DTC	Description	Status
B1476	IG1(A) voltage extraordinary low	Stored DTC

Meter (1 DTC)

DTC	Description	Status
-----	-------------	--------

B1201	Fuel information problem	Active DTC
-------	--------------------------	------------

4WS/Electric Power Steering (2 DTCs)

DTC	Description	Status
C1564	Vehicle speed data invalid	Stored DTC
C1537	Ignition signal fault	Stored DTC

Technician Notes
2016939597

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.