AUTEL

Shop: DEKRA MFC

Tel: --Email: --

Address: MFC Auction House

Kempton Park

Report ID: MAXIA20240221124635 Test Time: 2024-02-21 12:46:35

Technician: Sbu

Honda VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Honda/CR-V/--VIN: MRHRM1750EP000027

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Device information

Scanner: MaxiSys MS906 BT

Version: V9.20

Odometer Reading: 43303km License Plate: HDH719MP

Tel: 0861033572

Serial Number: VB8GJCC01482

Repair Order Number: --

System Scanned(8)

System	Status/DTC
Engine-PGM FI	② 0
ABS/TCS/VSA	Q 1
SRS	② 0
Gauges	② 0
EVPS	② 0
Body electrical	APAS O
IMMOBI	② 0
EPS	Q 1

▲ DTC (2)

ABS/TCS/VSA (1 DTC)

DTC	Description	Status		
61-12	Modulator-control unit power source circuit (IG) low voltage	Permanent DTC		
EPS (1 DTC)				
DTC	Description	Status		
11-02	Control Unit Power Supply Voltage	Permanent DTC		

AUTEL www.autel.com MaxiSys N

MaxiSys MS906 BT Page 1

/Honda/CR-V	Tact Time	2024-02-21 12:46:35	Report ID:	MAXIA20240221124635
/ Horiua/ Gri- v	i cot i iiiic.	2024-02-21 12.40.33	neport ib.	IVIANIAZUZAUZZI I ZAUJ

Technician Notes

2016276249

Customer name:	
Technician:	
Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys MS906 BT Page 2