

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/CLIO IV/--

VIN: VF15RSV0A61491969

Odometer Reading: 106933

License Plate: HZK428FS

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information











Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01482

Version: V12.00

Repair Order Number: --

System Scanned (9)

System	Status/DTC
Injection	 2
ABS	 1
Airbag / pretensioners	 0
Instrument panel	 4
UCH	 0
Variable PAS	 1
Radio	  3
Air conditioning	 0
Hands-free module	 0

DTC (11)

Injection (2 DTCs)

DTC	Description	Status
DTC01152F	Water temperature sensor circuit Micro-breaks.	Memory
DTC226321	Boost pressure circuit Turbocharging pressure is too high.	Memory

ABS (1 DTC)

DTC	Description	Status
DTCF00316	Computer power supply Circuit voltage below threshold	Memory

Instrument panel (4 DTCs)

DTC	Description	Status
DTC94011C	Oil level sensor circuit Battery voltage outside range	Memory
DTC94017B	Oil level sensor circuit Below the min level	Memory
DTC940413	Airbag fault warning light circuit Open circuit	Memory
DTC940811	Seat belt warning light circuit Short circuit to earth.	Memory

Variable PAS (1 DTC)

DTC	Description	Status
DTCF00313	Computer power supply Open circuit	Memory

Radio (3 DTCs)

DTC	Description	Status
DTC932813	Microphone Open circuit	Memory
DTC934149	Computer configuration Internal electronic fault	Memory
DTC93CF73	Key jammed Internal electronic fault	Memory

Technician Notes

2016205029

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.