

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/CLIO IV/--

VIN: VF15RSV0A62903372

Odometer Reading: 120642

License Plate: JD59JHGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01482

Version: V12.00

Repair Order Number: --

System Scanned (9)

System	Status/DTC
Injection	5
ABS	6
Airbag / pretensioners	4
Instrument panel	8
UCH	7
Variable PAS	3
Radio	5
Air conditioning	2
Hands-free module	4

DTC (44)

Injection (5 DTCs)

DTC	Description	Status
DTC021798	Engine overheating Operation temperature too high.	Memory
DTC056016	Computer supply voltage Permanent low level	Memory
DTC061A61	Computer Internal electronic fault	Memory
DTC083362	Clutch switch signal consistency	Memory
DTC224412	Proportional richness sensor circuit Short-circuit to +12V	Memory

ABS (6 DTCs)

DTC	Description	Status
DTC406C13	Vacuum sensor circuit Open circuit	Memory
DTC406C96	Vacuum sensor circuit Internal component failure	Memory
DTCC40100	Invalid INJ. Multiplex signals	Memory
DTCC42200	Invalid UCH multiplex signals	Memory
DTCF00316	Computer power supply Circuit voltage below threshold	Memory
DTCF00317	Computer power supply Circuit voltage above threshold	Memory

Airbag / pretensioners (4 DTCs)

DTC	Description	Status
DTC80D223	Warning light circuit fault	Memory
DTC80D224	Warning light circuit fault	Memory
DTC903616	Power supply voltage	Memory
DTC903617	Power supply voltage	Memory

Instrument panel (8 DTCs)

DTC	Description	Status
DTC94011C	Oil level sensor circuit Battery voltage outside range	Memory
DTC94017B	Oil level sensor circuit Below the min level	Memory
DTC940413	Airbag fault warning light circuit Open circuit	Memory
DTC940811	Seat belt warning light circuit Short circuit to earth.	Memory
DTC941211	External temperature sensor circuit Short circuit to earth.	Memory
DTC941213	External temperature sensor circuit Open circuit	Memory
DTCC00187	CAN communication Signal missing.	Memory
DTCF00316	Battery voltage 12 V Feed voltage too low	Memory

UCH (7 DTCs)

DTC	Description	Status
DTC951924	Neutral switch	Memory

DTC952014	Starter relay Open circuit or short circuit to earth	Memory
DTC953018	Left indicator circuit	Memory
DTC953118	Right indicator circuit Circuit current below threshold	Memory
DTC956023	Start of clutch switch travel circuit	Memory
DTC956123	End of clutch switch travel circuit	Memory
DTC95A064	Rear screen wiper circuit	Memory

Variable PAS (3 DTCs)

DTC	Description	Status
DTC560696	Variable power steering motor Internal electronic fault	Memory
DTCF00313	Computer power supply Open circuit	Memory
DTCF00316	Computer power supply Low voltage	Memory

Radio (5 DTCs)

DTC	Description	Status
DTC931513	FM1 receiver Open circuit	Memory
DTC932813	Microphone Open circuit	Memory
DTC934149	Computer configuration Internal electronic fault	Memory
DTC934262	Unit locked System jammed	Memory
DTC93CF73	Key jammed Internal electronic fault	Memory

Air conditioning (2 DTCs)

DTC	Description	Status
DTC910549	Computer Internal electronic fault	Memory
DTCF00316	Computer supply voltage Low voltage	Memory

Hands-free module (4 DTCs)

DTC	Description	Status
DTCA0334A	Dongle	Memory

DTCA05111	Steering lock Short circuit to earth.	Memory
DTCA0571C	Steering column lock protection Component failures	Memory
DTCA06004	Wake up signal Internal fault	Memory

Technician Notes

2016213150

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.