



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250522150544
Test Time: 2025-05-22 15:05:44
Technician: Andrick

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/CLIO IV/--
VIN: VF15RSV0A63319651

Odometer Reading: 102784
License Plate: JF99NHGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(10)

System	Status/DTC
Injection	 3
ABS	 5
Airbag / pretensioners	 5
Instrument panel	 4
UCH	 3
Variable PAS	 2
Radio	  8
Air conditioning	 1
Multimedia interface	 0
Hands-free module	 5

DTC (36)

Injection (3 DTCs)

DTC	Description	Status
DTC001177	Inlet camshaft shifter Assistance fault	Memory
DTC0226F1	Accelerator pedal position Jammed accelerator pedal detected.	Memory
DTC226322	Boost pressure circuit Turbocharging pressure is too low.	Memory

ABS (5 DTCs)

DTC	Description	Status
-----	-------------	--------



DTC403713	Rear left hand wheel speed sensor circuit Open circuit	Active
DTC403997	Rear right wheel target Component or system operation blocked or jammed	Active
DTC406C13	Vacuum sensor circuit Open circuit	Memory
DTCC40100	Invalid INJ. Multiplex signals	Memory
DTCF00316	Computer power supply Circuit voltage below threshold	Memory

Airbag / pretensioners (5 DTCs)

DTC	Description	Status
DTC800113	Driver's front air bag circuit 1 Open circuit	Active
DTC801013	Passenger front airbag circuit 1 Open circuit	Active
DTC902913	Front left-hand inertia wheel circuit Open circuit	Active
DTC902A13	Front right-hand inertia wheel circuit Open circuit	Active
DTC92B597	Front impact sensor	Active

Instrument panel (4 DTCs)

DTC	Description	Status
DTC940113	Oil level sensor circuit Open circuit	Active
DTC94011C	Oil level sensor circuit Battery voltage outside range	Memory
DTCC00187	CAN communication Signal missing.	Memory
DTCF00316	Battery voltage 12 V Feed voltage too low	Memory

UCH (3 DTCs)

DTC	Description	Status
DTC952014	Starter relay Open circuit or short circuit to earth	Memory
DTC953018	Left indicator circuit	Active
DTC953118	Right indicator circuit Circuit current below threshold	Memory

Variable PAS (2 DTCs)

DTC	Description	Status
DTCD00186	ABS multiplexed information invalid No multiplex signal	Active
DTCF00313	Computer power supply Open circuit	Memory

Radio (8 DTCs)

DTC	Description	Status
DTC930B13	Right rear speaker Open circuit	Active
DTC930D13	Right front speaker Open circuit	Active
DTC930F13	Left front speaker Open circuit	Active
DTC931113	Left rear speaker Open circuit	Active
DTC931513	FM1 receiver Open circuit	Active
DTC932813	Microphone Open circuit	Memory
DTC934262	Unit locked Computer locked	Memory
DTC93F016	Battery voltage 12 V Circuit voltage below threshold	Memory

Air conditioning (1 DTC)

DTC	Description	Status
DTCF00316	Computer supply voltage Low voltage	Memory

Hands-free module (5 DTCs)

DTC	Description	Status
DTCA0334A	Dongle	Memory
DTCA05111	Steering lock Short circuit to earth.	Memory
DTCA05297	Steering column lock protection Short circuit	Active
DTCA0571C	Steering column lock protection Component failures	Memory
DTCA06004	Wake up signal Internal fault	Memory

Technician Notes

2016887184

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.