

Shop Name: Dekra MFC Auction House Tel: --Email: --Address: MFC AUCTION HOUSE M57 PRETORIA ROAD KEMPTON PARK Report ID: MAXIA20250407134743 Test Time: 2025-04-07 13:47:43 Technician: Sbu

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/LOGAN II/SANDERO II/--VIN: VF15SRAAC56972120

Customer Information

Name: Dekra MFC AUCTION HOUSE

Device information

Scanner: MaxiSys MS906 BT Version: V14.10 Odometer Reading: 188820 License Plate: FX17TCGP

Tel: 0861033572

Serial Number: VB8GJCC01514 Repair Order Number: --

🔁 System Scanned(7)

| System | | Status/DTC |
|------------------------|------|------------|
| Injection | | S 9 |
| ABS | | 3 2 |
| Airbag / pretensioners | | Q 1 |
| Instrument panel | | 3 2 |
| UCH | | 3 2 |
| Variable PAS | | Q 1 |
| Radio | ADAS | v 0 |

🔼 DTC (17)

Injection (9 DTCs)

| DTC | Description | Status |
|-----------|---|--------|
| DTC030166 | Misfire on cylinder 1 Destructive misfiring. | Memory |
| DTC0301F8 | Misfire on cylinder 1 Polluting misfiring. | Memory |
| DTC030366 | Misfire on cylinder 3 Destructive misfiring. | Memory |
| DTC0303F8 | Misfire on cylinder 3 Polluting misfiring. | Memory |
| DTC031366 | Low fuel misfiring Destructive misfiring. | Memory |
| DTC0313F8 | Low fuel misfiring Polluting misfiring. | Memory |

/Renault/LOGAN II/SANDERO II

Test Time: 2025-04-07 13:47:43

Report ID: MAXIA20250407134743

| DTC035113 | Cylinder 1 ignition coil circuit Open circuit | Memory |
|----------------------|--|--------|
| DTC042009 | Catalytic converter functional fault Component in poor condition. | Memory |
| DTC226322 | Boost pressure circuit Turbocharging pressure is too low. | Active |
| ABS (2 DTCs) | | |
| DTC | Description | Status |
| DTCC40100 | Invalid INJ. Multiplex signals | Memory |
| DTCC42200 | Invalid UCH multiplex signals | Memory |
| Airbag / pretensi | ioners (1 DTC) | |
| DTC | Description | Status |
| DTC80D224 | Warning light circuit fault Inconsistency between the warning light status transmitted by the instrument panel and the request made by the airbag computer. | Memory |
| Instrument pane | l (2 DTCs) | |
| DTC | Description | Status |
| DTC94037B | Brake fluid level circuit Below the min level | Memory |
| DTCF00316 | Battery voltage 12 V Feed voltage too low | Memory |
| UCH (2 DTCs) | | |
| DTC | Description | Status |
| DTC953118 | Right indicator circuit Circuit current below threshold | Memory |
| DTC956023 | Start of clutch switch travel circuit | Memory |
| Variable PAS (1 DTC) | | |
| DTC | Description | Status |
| DTC560851 | Computer Fault | Memory |

Technician Notes 2016833048

Test Time: 2025-04-07 13:47:43

Report ID: MAXIA20250407134743

| Customer name: _ | |
|------------------|--|
| Technician: _ | |
| Date: _ | |

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.