



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250526155227
Test Time: 2025-05-26 15:52:27
Technician: Sbu

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/DUSTER PH3/--
VIN: VF1HJD20368633556

Odometer Reading: 84289
License Plate: KS63DHGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(14)

System		Status/DTC
Injection		 2
Automatic gearbox		 0
ABS		 1
Airbag / pretensioners		 0
Instrument panel		 0
UCH		 2
Communications unit		 0
Blind spot detection		 2
Variable PAS		 1
UPC		 1
Around view monitoring		 0
Central gateway		 0
Air conditioning		 0
Hands-free module		 0

DTC (9)

Injection (2 DTCs)

DTC	Description	Status
DTC0226F1	Brake/accelerator pedal positions Safety mode 1 flag	Memory



DTC061A61	Computer Signal calculation failure	Memory
-----------	--	--------

ABS (1 DTC)

DTC	Description	Status
DTCC40200	Multiplexed auto trans information invalid	Memory

UCH (2 DTCs)

DTC	Description	Status
DTC953018	Left indicator circuit	Memory
DTC953118	Right indicator circuit	Memory

Blind spot detection (2 DTCs)

DTC	Description	Status
DTCA73097	Front right-hand lateral sensor Component or system operation blocked or jammed	Memory
DTCA73811	Sensor supply voltage Circuit short to ground	Memory

Variable PAS (1 DTC)

DTC	Description	Status
DTC561854	Steering wheel angle sensor programming Calibration absent	Memory

UPC (1 DTC)

DTC	Description	Status
DTC923897	Windscreen wiper motor Component or system operation blocked or jammed	Memory

Technician Notes
2016891201

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.