AUTEL

Shop: DEKRA MFC

Tel: --Email: --

Address: MFC Auction House

Kempton Park

Report ID: MAXIA20240216114730 Test Time: 2024-02-16 11:47:30

Technician: Sbu

Peugeot VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Peugeot/308/--VIN: VF3LPHNZBFS247656

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Device information

Scanner: MaxiSys MS906 BT

Version: V8.50

Odometer Reading: 98676 License Plate: JZX581MP

Tel: 0861033572

Serial Number: VB8GJCC01482

Repair Order Number: --

🔁 System Scanned(17)

Built-in Systems Interface (BSI) BSI2010 Engine ECU VD46 ABS or ESP ESP90 Airbags and pretensioners ECU RBG_UDS Combination instrument COMBINE_UDS A/C BCC Voltage stabilizer DMTR_DTC3B Power steering DAE_BVH2 Battery State Of Charge (SOC) control unit BECB_GEN2 Controls under the steering wheel COM2008P Steering wheel controls / Integral controls steering wheel VCI Multi-function control panel FMUX Seatbelt not fastened warning lamps unit TNB_2010 Touchscreen EMF_DGT_UDS Anti-theft alarm MUS	System	Status/DTC
ABS or ESP ESP90 Airbags and pretensioners ECU RBG_UDS 6 Combination instrument COMBINE_UDS 3 A/C BCC 0 Voltage stabilizer DMTR_DTC3B 3 Power steering DAE_BVH2 0 Battery State Of Charge (SOC) control unit SECB_GEN2 Controls under the steering wheel COM2008P Steering wheel controls / Integral controls steering wheel VCI Multi-function control panel FMUX Seatbelt not fastened warning lamps unit TNB_2010 Touchscreen EMF_DGT_UDS 4 Badio navigation or telematic unit (RTx) SMEG_PLUS	Built-in Systems Interface (BSI) BSI2010	3 28
Airbags and pretensioners ECU RBG_UDS Combination instrument COMBINE_UDS 3 A/C BCC Voltage stabilizer DMTR_DTC3B Power steering DAE_BVH2 Battery State Of Charge (SOC) control unit BECB_GEN2 Controls under the steering wheel COM2008P Steering wheel controls / Integral controls steering wheel VCI Multi-function control panel FMUX Seatbelt not fastened warning lamps unit TNB_2010 Touchscreen EMF_DGT_UDS Adams of the steering wheel controls of the ste	Engine ECU VD46	O
Combination instrument COMBINE_UDS A/C BCC Voltage stabilizer DMTR_DTC3B S 3 Power steering DAE_BVH2 © 0 Battery State Of Charge (SOC) control unit SECB_GEN2 Controls under the steering wheel COM2008P Steering wheel controls / Integral controls steering wheel VCI Multi-function control panel FMUX Seatbelt not fastened warning lamps unit TNB_2010 Touchscreen EMF_DGT_UDS A 3 Radio navigation or telematic unit (RTx) SMEG_PLUS	ABS or ESP ESP90	O
A/C BCC Voltage stabilizer DMTR_DTC3B Power steering DAE_BVH2 Battery State Of Charge (SOC) control unit BECB_GEN2 Controls under the steering wheel COM2008P Steering wheel controls / Integral controls steering wheel VCI Multi-function control panel FMUX Seatbelt not fastened warning lamps unit TNB_2010 Touchscreen EMF_DGT_UDS ABadio navigation or telematic unit (RTx) SMEG_PLUS	Airbags and pretensioners ECU RBG_UDS	Q 6
Voltage stabilizer DMTR_DTC3B Power steering DAE_BVH2 Battery State Of Charge (SOC) control unit BECB_GEN2 Controls under the steering wheel COM2008P Steering wheel controls / Integral controls steering wheel VCI Multi-function control panel FMUX 6 Seatbelt not fastened warning lamps unit TNB_2010 Touchscreen EMF_DGT_UDS A Radio navigation or telematic unit (RTx) SMEG_PLUS	Combination instrument COMBINE_UDS	3
Power steering DAE_BVH2 Battery State Of Charge (SOC) control unit BECB_GEN2 Controls under the steering wheel COM2008P Steering wheel controls / Integral controls steering wheel VCI Multi-function control panel FMUX Seatbelt not fastened warning lamps unit TNB_2010 Touchscreen EMF_DGT_UDS ABAGio navigation or telematic unit (RTx) SMEG_PLUS O O O O O O O O O O O O O	A/C BCC	O
Battery State Of Charge (SOC) control unit BECB_GEN2 Controls under the steering wheel COM2008P Steering wheel controls / Integral controls steering wheel VCI Multi-function control panel FMUX Seatbelt not fastened warning lamps unit TNB_2010 Touchscreen EMF_DGT_UDS A Radio navigation or telematic unit (RTx) SMEG_PLUS	Voltage stabilizer DMTR_DTC3B	3
Controls under the steering wheel COM2008P Steering wheel controls / Integral controls steering wheel VCI Multi-function control panel FMUX Seatbelt not fastened warning lamps unit TNB_2010 Touchscreen EMF_DGT_UDS Addio navigation or telematic unit (RTx) SMEG_PLUS	Power steering DAE_BVH2	② 0
Steering wheel controls / Integral controls steering wheel VCI Multi-function control panel FMUX Seatbelt not fastened warning lamps unit TNB_2010 Touchscreen EMF_DGT_UDS A Radio navigation or telematic unit (RTx) SMEG_PLUS		Q 1
wheel VCI Multi-function control panel FMUX Seatbelt not fastened warning lamps unit TNB_2010 Touchscreen EMF_DGT_UDS Radio navigation or telematic unit (RTx) SMEG_PLUS	Controls under the steering wheel COM2008P	3
Seatbelt not fastened warning lamps unit TNB_2010 Touchscreen EMF_DGT_UDS Radio navigation or telematic unit (RTx) SMEG_PLUS O 0	Steering wheel controls / Integral controls steering wheel VCI	Q 1
TNB_2010 Touchscreen EMF_DGT_UDS Radio navigation or telematic unit (RTx) SMEG_PLUS 0	Multi-function control panel FMUX	Q 6
Radio navigation or telematic unit (RTx) SMEG_PLUS	Seatbelt not fastened warning lamps unit TNB_2010	O
SMEG_PLUS	Touchscreen EMF_DGT_UDS	Q 4
Anti-theft alarm MUS © 0	Radio navigation or telematic unit (RTx) SMEG_PLUS	O
	Anti-theft alarm MUS	② 0

MaxiSys MS906 BT

Page 1

Intrusion alarm siren -- SIR



DTC (55)

Built-in Systems Interface (BSI) -- BSI2010 (28 DTCs)

Built-in System	s Interface (BSI) BSI2010 (28 DTCs)	
DTC	Description	Status
B1808:87	Fault in unlocking of immobilizer by engine ECU Request missing	Intermittent
U1802:86	Vehicle speed data fault Signal invalid	Intermittent
B1163:15	Fault in license plate lighting control Circuit open or short to positive	Intermittent
B1627:14	Battery State Of Charge (SOC) unit : Voltage sensor fault	Intermittent
B1715:64	Inconsistency between vehicle locking status and locking status of right front door lock Inconsistency	Intermittent
B1716:64	Inconsistency between vehicle locking status and locking status of left front door lock Inconsistency	Intermittent
B1702:11	Control fault of door locking motors Short circuit to ground	Intermittent
B171D:62	Fault in status of left front lock (lock closed but declared open) Consistency	Intermittent
B1805:62	Starter fault Consistency	Intermittent
B1816:87	Loss of hybrid drivetrain status information or of starting authorization information from engine ECU	Intermittent
C1651:86	Confirmation of the taking into account of the indirect tire under-inflation detection function reference drives lib reinitialization request Confirmation not emitted by the ESP or not taken into account by the Built-in Systems Interface (BSI)	Intermittent
B173A:00	Fault in driver door status for determination of driver presence	Intermittent
B1418:00	Fault in seatbelt fastening information status for determining presence of driver	Present
B1825:84	Oil level information fault Level too low	Intermittent
U1809:81	Oil temperature information fault Signal invalid	Intermittent
B132F:81	Fault in A/C high pressure information Value invalid	Intermittent
U1F15:08	ECU not communicating on entertainment information CAN	Intermittent
U1F0E:88	Transmission and reception fault on the inter-systems CAN/ High speed CAN 1	Intermittent
U1F00:00	Error information lost	Present
U1F1B:08	Fault in LIN 2	Intermittent

MaxiSys MS906 BT

/Peugeot/308	Test Time: 2024-02-16 11:47:30	Report ID: MAXIA2024021611473	
B162B:11	CAN positive relay control and status inconsistent Relay controlled But Inactive	Present	
U1F40:87	No communication with battery State Of Charge (SOC) control unit	Intermittent	
U1F43:87	No communication with airbags and pre-tensioners unit	Intermittent	
U1F3E:87	No communication with telematics ECU	Intermittent	
U1F42:87	No communication with A/C ECU	Intermittent	
U1F25:87	No communication with instrument cluster	Intermittent	
U1F2E:87	No communication with engine ECU	Intermittent	
U1F27:87	No communication with multi-function control panel	Intermittent	
Airbags and pr	etensioners ECU RBG_UDS (6 DTCs)		
DTC	Description	Status	
B1400:16	CAN + supply voltage fault Voltage too low	Intermittent	
B1400:64	CAN + supply voltage fault Not characterized	Intermittent	
B00D5:67	Passenger airbag deactivation warning lamp fault Not characterized	Intermittent	
B00D2:67	Fault in airbags and pretensioners fault warning lamp Not characterized	Intermittent	
U1802:81	Vehicle speed data fault Data received invalid	Intermittent	
U1F00:00	Fault not recorded in the Built-in Systems Interface (BSI) error information Not characterized	Intermittent	
Combination ir	nstrument COMBINE_UDS (3 DTCs)		
DTC	Description	Status	
B1003 54	Configuration fault (Warning! This may be a phantom fault) No calibration	Present	
U1F03 87	No communication with the Built-in Systems Interface (BSI)	Intermittent	
U1F00 00	Fault not recorded in the Built-in Systems Interface (BSI) error information	Present	
Voltage stabiliz	zer DMTR_DTC3B (3 DTCs)		
DTC	Description	Status	
B1004	Network voltage stabilizer internal fault	Intermittent	
P1B71	Triggering line fault in network voltage stabilizer Circuit open or short to ground	Intermittent	
U1F2E	No communication with the engine ECU	Intermittent	

Battery State Of Charge (SOC) control unit -- BECB_GEN2 (1 DTC)

AUTEL www.autel.com MaxiSys MS906 BT Page 3

/Peugeot/308	Test Time: 2024-02-16 11:47:30 Report ID: MAXIA202402161147		
DTC	Description	Status	
B1627	Battery State Of Charge (SOC) unit : Voltage sensor fault	Intermittent	
Controls under	r the steering wheel COM2008P (3 DTCs)		
DTC	Description	Status	
B1182:64	Windshield wiping or washing controls fault Internal fault	Intermittent	
B100C:16	ECU supply fault Voltage too low	Intermittent	
U1F00:00	Event not recorded	Permanent	
Steering whee	controls / Integral controls steering wheel VCI (1 DTC)		
DTC	Description	Status	
U1F1A 87	Fault in transmission by top-of-column on LIN	Intermittent	
Multi-function	control panel FMUX (6 DTCs)		
DTC	Description	Status	
U1F3E 87	Touchscreen: No communication with telematics unit	Intermittent	
U1F18 88	Touchscreen not communicating on the multimedia CAN	Intermittent	
B1004 1C	Multi-function control panel or touchscreen Touchscreen : Voltage out of range	Intermittent	
U1F0A 88	Multi-function control panel or touchscreen Fault: CAN	Intermittent	
U1F00 00	Event not recorded	Intermittent	
U1F2B 87	No communication with telematics navigator	Intermittent	
Touchscreen -	- EMF_DGT_UDS (4 DTCs)		
DTC	Description	Status	
B1004 1C	Touchscreen internal fault Voltage out of range	Intermittent	
U1F3E 87	No communication with telematics unit	Intermittent	
U1F18 88	Touchscreen not communicating on the multimedia CAN	Intermittent	

AUTEL www.autel.com MaxiSys MS906 BT Page 4

Intermittent

CAN fault

U1F0A 88

/Peugeot/308	Toot Time	2024-02-16 11:47:30	Papart ID:	MAXIA20240216114730
/ r eugeot/ 300	rest rille.	2024-02-10 11.47.30	neport ib.	IVIANIAZUZAUZTUTTATSU

Technician Notes

2016270971

Customer name:	
Technician:	
Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

AUTEL www.autel.com

MaxiSys MS906 BT Page 5