

Shop: Dekra MFC Auction House

Tel: --Email: --

Address: MFC AUCTION HOUSE

M57 PRETORIA ROAD KEMPTON PARK Report ID: MAXIA20240801093155 Test Time: 2024-08-01 09:31:55

Technician: Andrick

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Yaris/-- Odometer Reading: 161005 VIN: VNKKL0D340A006115 License Plate: FH31JSGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Device information

Scanner: MaxiSys MS906 BT Serial Number: VB8GJCC01514

Version: V11.00 Repair Order Number: --

🔁 System Scanned(6)

System	Status/DTC
Engine and ECT	O
ABS/VSC/TRC	O
Combination meter	Q 1
Main body	Q 4
Air conditioner	Q 3
Charging control	② 0

Tel: 0861033572

▲ DTC (8)

DTC

U0151

Combination meter (1 DTC)

Description

Main body (4 DTCs)DTCDescriptionStatusB1269Theft deterrent ECU communication stopCurrentB1269Theft deterrent ECU communication stopHistory	U0100	Lost communication with ECM/PCM/EV "A"	History
B1269 Theft deterrent ECU communication stop Current	Main body (4 DTCs)		
<u> </u>	DTC	Description	Status
B1269 Theft deterrent ECU communication stop History	B1269	Theft deterrent ECU communication stop	Current
	B1269	Theft deterrent ECU communication stop	History
U0100 Lost communication with ECM/PCM/EV "A" History	U0100	Lost communication with ECM/PCM/EV "A"	History

Air conditioner (3 DTCs)

DTC	Description	Status
B1412	Ambient temperature sensor circuit	History
U0100	Lost communication with ECM/PCM/EV "A"	History

Lost communication with restraints control module

www.autel.com

MaxiSys MS906 BT Page 1

Status

History

/Toyota/Yaris	Test Time: 2024-08-01 09:31:55	Report ID: MAXIA20240801093155
U0142	Lost communication with body control module (BCM) B	History

Technician Notes

2016476675

Customer name:	
Technician:	
Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys MS906 BT Page 2