



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250109145407
Test Time: 2025-01-09 14:54:07
Technician: Travino

Opel VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Opel/Corsa-E/--
VIN: W0V0XEP68K4502379

Odometer Reading: 158549
License Plate: JH06PFGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V9.20

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(8)

System	Status/DTC
Engine control module	 5
Electronic brake control module	 0
Chassis control module	 0
Inflatable restraint sensing and diagnostic module	 0
Instrument cluster	 0
Power steering control module	 0
Body control module	 7
Radio	 0

DTC (12)

Engine control module (5 DTCs)

DTC	Description	Status
P0011:00	Intake camshaft position system performance	DTC history status : History Since DTC clear : Passed and failed Last test : Passed This ignition cycle : Passed MIL status : Not requested

P0014:00	Exhaust camshaft position system performance	DTC history status : History Since DTC clear : Passed and failed Last test : Passed This ignition cycle : Passed MIL status : Not requested
P0016:00	Crankshaft position - intake camshaft position not plausible	DTC history status : History Since DTC clear : Passed and failed Last test : Passed This ignition cycle : Passed MIL status : Not requested
P0299:00	Engine underboost	DTC history status : History Since DTC clear : Passed and failed Last test : Passed This ignition cycle : Not run MIL status : Requested
P0420:00	Catalyst system low efficiency	DTC history status : History Since DTC clear : Failed Last test : Failed current DTC This ignition cycle : Not run MIL status : Requested

Body control module (7 DTCs)

DTC	Description	Status
B2545:04	Backup lamps circuit - Open	DTC history status : History Since DTC clear : Failed Last test : Failed current DTC This ignition cycle : Not run MIL status : Not requested

B260B:04	Left low beam power circuit - Open	DTC history status : History Since DTC clear : Passed and failed Last test : Failed current DTC This ignition cycle : Failed MIL status : Not requested
B3055:00	No transponder modulation or no transponder - Malfunction	DTC history status : History Since DTC clear : Passed and failed Last test : Passed This ignition cycle : Passed MIL status : Not requested
B3125:02	Driver door only unlock circuit - Short to ground	DTC history status : History Since DTC clear : Passed and failed Last test : Passed This ignition cycle : Passed MIL status : Not requested
B3130:02	All doors unlock circuit - Short to ground	DTC history status : History Since DTC clear : Passed and failed Last test : Passed This ignition cycle : Passed MIL status : Not requested
B3135:02	All doors lock circuit - Short to ground	DTC history status : History Since DTC clear : Passed and failed Last test : Passed This ignition cycle : Passed MIL status : Not requested

C0750:29 Left front tire pressure sensor - Too few pulses

DTC history status :
History
Since DTC clear : Passed
and failed
Last test : Failed current
DTC
This ignition cycle : Failed
MIL status : Not requested

Technician Notes
2016713971

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.