



Shop Name: Dekra MFC Auction House

Tel: --

Email: --

Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20241101103752

Test Time: 2024-11-01 10:37:52

Technician: Andrick

# Volkswagen CV VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Volkswagen CV/2H/S1 - Amarok 2010 >/--

VIN: WV1ZZZ2HZDA064136

Odometer Reading: 142161

License Plate: HNJ863FS

## Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

## Device information

















Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01514

Version: V21.00

Repair Order Number: --

## System Scanned( 15 )

System	Status/DTC
01 - Engine Control Module 1	 3
02 - Transmission electronics	 0
03 - Brakes 1	 1
08 - Air Conditioning	 1
09 - Electronic central electric	 7
10 - Parallel parking 2	  0
15 - Airbag	 0
17 - Instrument cluster	 0
19 - Gateway	 0
25 - Anti-Theft Immobilizer	 0
32 - Lock Electronics	 0
56 - Radio	 0
61 - Battery Regulation	 0
69 - Trailer Function	 2
77 - Telephone	 1

## DTC ( 15 )

### 01 - Engine Control Module 1 ( 3 DTCs )

DTC	Description	Status
-----	-------------	--------

P008700	Fuel rail/system pressure - too low	Passive/Sporadic
U015500	Lost communication with instrument cluster control unit	Passive/Sporadic
P068A00	ECM/PCM Power Relay De-Energized Performance - Too Early	Active/static

**03 - Brakes 1 ( 1 DTC )**

DTC	Description	Status
00668:001	Vehicle voltage terminal 30 - Upper limit exceeded	Passive/Sporadic

**08 - Air Conditioning ( 1 DTC )**

DTC	Description	Status
B108B71	Fresh air recirculation, air flow flap motor ,Actuator stuck	Passive/Sporadic

**09 - Electronic central electric ( 7 DTCs )**

DTC	Description	Status
03304:008	Return message for right rear door closing condition - Implausible signal	Passive/Sporadic
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
01598:000	Drive battery voltage	Passive/Sporadic
01134:004	Alarm horn - No signal/communication	Active/static
00538:011	Reference voltage - Open circuit	Passive/Sporadic
02660:000	Radio Remote control operation not adapted	Passive/Sporadic

**69 - Trailer Function ( 2 DTCs )**

DTC	Description	Status
02564:010	Bulb for left tail light on trailer - Open circuit/short circuit to B+	Active/static
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic

**77 - Telephone ( 1 DTC )**

DTC	Description	Status
B105213	Cell phone prep. ctrl. head/emergency call module ,Open circuit	Passive/Sporadic

## Technician Notes

2016595023

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.

*Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.*