



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250508161101
Test Time: 2025-05-08 16:11:01
Technician: Werner

Volkswagen CV VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen CV/S6/S7 - Amarok 2017 >/--
VIN: WV1ZZZ2HZJA001861

Odometer Reading: 289880km
License Plate: LM95VGGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V22.00

Serial Number: VB8GJCC01514
Repair Order Number: --



System Scanned(15)

System	Status/DTC
01 - Engine Control Module 1	2
02 - Transmission electronics	1
03 - Brakes 1	2
04 - Steering Angle Sender	1
08 - Air Conditioning	1
09 - Electronic central electric	3
10 - Parallel parking 2	1
15 - Airbag	1
17 - Instrument cluster	0
19 - Gateway	1
25 - Anti-Theft Immobilizer	0
32 - Lock Electronics	1
5F - Information electronics 1	1
61 - Battery Regulation	0
69 - Trailer Function	1



DTC (16)

01 - Engine Control Module 1 (2 DTCs)

DTC	Description	Status
P019600	Oil temperature sensor circuit Range/performance	Passive/Sporadic



P159D00	Oil level/temperature sensor Range/performance	Passive/Sporadic
---------	---	------------------

02 - Transmission electronics (1 DTC)

DTC	Description	Status
U015500	Lost communication with instrument cluster control unit	Passive/Sporadic

03 - Brakes 1 (2 DTCs)

DTC	Description	Status
U112100	Data bus message missing	Passive/Sporadic
U112300	Databus error value received	Passive/Sporadic

04 - Steering Angle Sender (1 DTC)

DTC	Description	Status
U112100	Data bus message missing	Passive/Sporadic

08 - Air Conditioning (1 DTC)

DTC	Description	Status
U111100	Function restriction caused by missing message	Passive/Sporadic

09 - Electronic central electric (3 DTCs)

DTC	Description	Status
03224:000	Play protection active	Passive/Sporadic
00975:011	Rear window defogger - Open circuit	Active/static
00077:004	Windshield wiper stop switch - No signal/communication	Passive/Sporadic

10 - Parallel parking 2 (1 DTC)

DTC	Description	Status
U111100	Function restriction caused by missing message	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
U112200	Data bus message implausible	Passive/Sporadic

19 - Gateway (1 DTC)

DTC	Description	Status
00381:004	Instrument cluster data bus - No signal/communication	Passive/Sporadic

32 - Lock Electronics (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

5F - Information electronics 1 (1 DTC)

DTC	Description	Status
U112100	Data bus message missing	Passive/Sporadic

69 - Trailer Function (1 DTC)

DTC	Description	Status
02564:010	Bulb for left tail light on trailer - Open circuit/short circuit to B+	Active/static

Technician Notes
2016870736

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.