Report ID: MAXIA20250724170455 Test Time: 2025-07-24 17:04:55

Technician: Sbu

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/Tiguan/--VIN: WVGZZZ5NZEW074471

Odometer Reading: 269700km License Plate: HHT676MP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Version: V22.50

Serial Number: VB8GJCC01509

Repair Order Number: --

🔀 System Scanned(17)

System	Status/DTC
01 - Engine Control Module 1	3
03 - Brakes 1	② 0
08 - Air Conditioning	② 0
09 - Electronic central electric	Q 4
15 - Airbag	② 0
16 - Steering column electronics	② 0
17 - Instrument cluster	② 0
19 - Gateway	② 0
20 - High beam assistant	Q 1
25 - Anti-Theft Immobilizer	② 0
42 - Driver's door electronics	② 0
44 - Power Steering	Q 1
52 - Passenger's door electronics	Q 1
53 - Parking Brake	Q 1
56 - Radio	Q 5
61 - Battery Regulation	Q 2
77 - Telephone	② 0

TOTE (18)

01 - Engine Control Module 1 (3 DTCs)

Description DTC **Status**

AUTEL www.autel.com

MaxiSys MS906 BT

Page 1

/Volkswagen/Tigu	Test Time: 2025-07-24 17:04:55	Report ID: MAXIA2025072417045		
P056200	System Voltage Low Voltage	Passive/Sporadic		
P003000	O2 Sensor Heater Contr. Circ.(Bank1(1)Sensor 1)	Active/static		
P029900	Turbocharger/supercharger underboost	Passive/Sporadic		
09 - Electronic	central electric (4 DTCs)			
DTC	Description	Status		
00446:002	Function limitation due to insufficient voltage - Lower limit not reached Passive/Sporadic			
01038:000	Central locking overheating protection	Passive/Sporadic		
01134:002	Alarm horn - Lower limit not reached	Passive/Sporadic		
01496:010	Left fog light bulb - Open circuit/short circuit to B+	Active/static		
20 - High beam	assistant (1 DTC)			
DTC	Description	Status		
03576:000	Control module for high beam assistant, limited visibility	Passive/Sporadic		
44 - Power Ste	ering (1 DTC)			
DTC	Description	Status		
00668:002	Vehicle voltage terminal 30 - Lower limit not reached	Passive/Sporadic		
52 - Passenger	's door electronics (1 DTC)			
DTC	Description	Status		
B11F401	Mirror adjustment motor Electrical fault	Active/static		
53 - Parking Br	ake (1 DTC)			
DTC	Description	Status		
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic		
56 - Radio (5 D	TCs)			
DTC	Description	Status		
00878:006	Connections to left speakers - Short circuit to B+	Passive/Sporadic		
00879:006	Connections to right speakers - Short circuit to B+	Passive/Sporadic		
00879:007	Connections to right speakers - Short circuit to ground	Passive/Sporadic		
00880:006	Connections to left rear speakers - Short circuit to B+	Passive/Sporadic		
00881:006	Connections to right rear speakers - Short circuit to B+	Passive/Sporadic		
61 - Battery Re	gulation (2 DTCs)			
DTC	Description	Status		
00458:004	Battery monitoring control module - No signal/communication	Passive/Sporadic		

AUTEL www.autel.com MaxiSys MS906 BT Page 2

/Volkswagen/Tigua	n	Test Time:	2025-07-24 17:04:55	Report ID:	MAXIA20250724170455
00458:014	Battery monitoring control	module -	Faulty	Active/s	tatic
Technician Not	es				

Customer name: _	
Technician: _	
Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

AUTEL www.autel.com

Al.com MaxiSys MS906 BT Page 3