



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250625090845
Test Time: 2025-06-25 09:08:45
Technician: Travino

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/BW - Tiguan 2018 USA/CAN >/--
VIN: WVGZZZ5NZJM217021

Odometer Reading: 130817km
License Plate: LCH503NW

Customer Information

Name: Dekra MFC AUCTION HOUSE




















Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V22.50

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(22)

System	Status/DTC
01 - Engine Control Module 1	 7
02 - Transmission electronics	 1
03 - Brakes 1	 2
08 - Air Conditioning	 1
09 - Electronic central electric	 3
15 - Airbag	 0
16 - Steering column electronics	 0
17 - Instrument cluster	 0
19 - Gateway	 0
20 - High beam assistant	 0
29 - Left light control	 0
39 - Light Control Right	 3
42 - Driver's door electronics	 1
44 - Power Steering	 2
4B - Multi-function module	 2
52 - Passenger's door electronics	 0
5F - Information electronics 1	 0
65 - Tire pressure monitoring	 0
69 - Trailer Function	 0



CA - Sunroof control module	✓ 0
D6 - Light Control Left 2	✓ 0
D7 - Light Control Right 2	✓ 0

DTC (22)

01 - Engine Control Module 1 (7 DTCs)

DTC	Description	Status
U112300	Databus error value received	Passive/Sporadic
P057200	Brake Switch 'A' Circuit Low	Active/static
U102600	Transmission control module Read out DTC	Active/static
U042800	Steering angle sensor Range/performance	Passive/Sporadic
P162400	Requirement - malfunction lamp on active	Active/static
P013400	O2 Sensor Circ.,Bank1-Sensor1 No Activity Detected	Active/static
P013500	O2 Sensor Heater Circ.,Bank1-Sensor1 Malfunction	Active/static

02 - Transmission electronics (1 DTC)

DTC	Description	Status
P174E00	Valve 3 in partial transmission 2 Electrical error	Passive/Sporadic

03 - Brakes 1 (2 DTCs)

DTC	Description	Status
C109E29	Gear R information Range/performance	Passive/Sporadic
B1168F2	Steering angle sensor no initialization	Passive/Sporadic

08 - Air Conditioning (1 DTC)

DTC	Description	Status
B10F000	Function restriction caused by compressor shut-off by engine	Passive/Sporadic

09 - Electronic central electric (3 DTCs)

DTC	Description	Status
U112300	Databus error value received	Active/static

B133029	Anti-theft alarm system sensor Range/performance	Passive/Sporadic
U119C00	Bulb 2 for roof contour lighting No communication	Active/static

39 - Light Control Right (3 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
U140000	Function restriction Caused by low voltage	Passive/Sporadic
C11F407	Adaptive cornering lamp servomotor Mechanical fault	Active/static

42 - Driver's door electronics (1 DTC)

DTC	Description	Status
B11FD13	Turn signal in exterior rear-view mirror Open circuit	Active/static

44 - Power Steering (2 DTCs)

DTC	Description	Status
B1168F2	Steering angle sensor no initialization	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic

4B - Multi-function module (2 DTCs)

DTC	Description	Status
U112300	Databus error value received	Passive/Sporadic
U112300	Databus error value received	Active/static

Technician Notes
2016924173

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.