



Shop: DEKRA MFC
 Tel: --
 Email: --
 Address: MFC Auction House
 Kempton Park

Report ID: MAXIA20240118155204
 Test Time: 2024-01-18 15:52:04
 Technician: Andrick

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/5K - Golf 2009 >/--
 VIN: WVWZZZ1KZCW074991

Odometer Reading: 77362
 License Plate: N o n e p l a t e n u m b e r

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE



















Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
 Version: V19.00

Serial Number: VB8GJCC01482
 Repair Order Number: --

System Scanned(17)

System	Status/DTC
01 - Engine Control Module 1	 9
03 - Brakes 1	 1
08 - Air Conditioning	 1
09 - Electronic central electric	 4
10 - Parallel parking 2	  0
15 - Airbag	 3
16 - Steering column electronics	 0
17 - Instrument cluster	 1
19 - Gateway	 1
22 - All-wheel drive electronics	 0
25 - Anti-Theft Immobilizer	 0
42 - Driver's door electronics	 0
44 - Power Steering	 0
52 - Passenger's door electronics	 0
56 - Radio	 0
62 - Left rear door electronics	 0
72 - Right rear door electronics	 0

 **DTC (20)**
01 - Engine Control Module 1 (9 DTCs)

DTC	Description	Status
P1250:08/04 688:008	Fuel level too low - Implausible signal	Active/static
P0243:04/00 579:004	Turbo/Super Charger Wastegate Solenoid A - No signal/communication	Active/static
P310B:02/12 555:002	Low Fuel Pressure regulation Fuel pressure outside specification - Lower limit not reached	Passive/Sporadic
P0087:02/00 135:002	Fuel Rail/System Pressure - Too Low - Lower limit not reached	Passive/Sporadic
P0300:01/00 768:001	Random/Multiple Cylinder Misfire Detected - Upper limit exceeded	Passive/Sporadic
P0301:01/00 769:001	Cyl.1 Misfire Detected - Upper limit exceeded	Passive/Sporadic
P119A:02/04 506:002	Fuel pressure sensor Malfunction - Lower limit not reached	Active/static
P008A:02/00 138:002	Low Pressure Fuel System Pressure - Too Low - Lower limit not reached	Passive/Sporadic
P130A:01/04 874:001	Hide cylinder - Upper limit exceeded	Passive/Sporadic

03 - Brakes 1 (1 DTC)

DTC	Description	Status
02214:002	Tire pressure warning - Lower limit not reached	Active/static

08 - Air Conditioning (1 DTC)

DTC	Description	Status
B10BE96	Fresh air blower, front Internal malfunction	Active/static

09 - Electronic central electric (4 DTCs)

DTC	Description	Status
01134:004	Alarm horn - No signal/communication	Active/static
03156:004	Anti-theft alarm system sensor - No signal/communication	Active/static
00924:009	Relay for headlamp washer system - Open circuit/short circuit to ground	Active/static
03266:009	Activation relay for signal horn - Open circuit/short circuit to ground	Active/static

15 - Airbag (3 DTCs)

DTC	Description	Status
B100B00	Driver thorax airbag igniter	Active/static
B100A00	Front passenger side-airbag igniter	Active/static
B200600	Control module does not match vehicle	Active/static

17 - Instrument cluster (1 DTC)

DTC	Description	Status
U111100	Function restriction caused by missing message	Active/static

19 - Gateway (1 DTC)

DTC	Description	Status
01771:004	Headlamp range control module - No signal/communication	Active/static

Technician Notes

2016234422

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.