



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250730125313
Test Time: 2025-07-30 12:53:13
Technician: Travino

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AU/BE/BX - Golf 2013 USA/CAN >--
VIN: WVWZZZAUZGW160271

Odometer Reading: 216807km
License Plate: FB81CWGP

Customer Information

Name: Dekra MFC AUCTION HOUSE




















Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V22.50

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(20)

System	Status/DTC
01 - Engine Control Module 1	 8
02 - Transmission electronics	 0
03 - Brakes 1	 2
08 - Air Conditioning	 1
09 - Electronic central electric	 2
15 - Airbag	 0
16 - Steering column electronics	 0
17 - Instrument cluster	 0
19 - Gateway	 1
20 - High beam assistant	 1
22 - All-wheel drive electronics	 0
2B - Steering Column Locking	 0
42 - Driver's door electronics	 1
44 - Power Steering	 0
52 - Passenger's door electronics	 1
55 - Headlight Regulation	 0
5F - Information electronics 1	 2
76 - Parking assistance	 0
A9 - Structure-Borne Sound Actuator	 0



B7 - Interface for access/start system

✓ 0

DTC (19)

01 - Engine Control Module 1 (8 DTCs)

DTC	Description	Status
P125000	Fuel level too low	Passive/Sporadic
P157000	Engine control unit disabled	Passive/Sporadic
P030300	Cylinder 3 Misfire detected	Passive/Sporadic
P030200	Cylinder 2 Misfire detected	Passive/Sporadic
P33B100	Cylinder 3 Combustion misfire detected during intake manifold injection	Passive/Sporadic
P33B000	Cylinder 2 Combustion misfire detected during intake manifold injection	Passive/Sporadic
P030000	Random/multiple cylinder Misfire detected	Passive/Sporadic
P034100	Camshaft Position Sensor Implausible signal	Passive/Sporadic

03 - Brakes 1 (2 DTCs)

DTC	Description	Status
C10CE29	AUTO HOLD button Range/performance	Passive/Sporadic
C102D00	Tire pressure warning	Passive/Sporadic

08 - Air Conditioning (1 DTC)

DTC	Description	Status
B10CD00	Function restriction caused by energy management	Passive/Sporadic

09 - Electronic central electric (2 DTCs)

DTC	Description	Status
B147918	Remote control key 1 Voltage too low	Active/static
B1330F5	Anti-theft alarm system sensor Alert - emergency activation stage 1	Passive/Sporadic

19 - Gateway (1 DTC)

DTC	Description	Status
U006500	Vehicle Communication Bus E Performance	Passive/Sporadic

20 - High beam assistant (1 DTC)

DTC	Description	Status
C10B2F1	Automatic high beam assist control unit Restricted view	Passive/Sporadic

42 - Driver's door electronics (1 DTC)

DTC	Description	Status
B177501	Door warning light / entry light Electrical error	Active/static

52 - Passenger's door electronics (1 DTC)

DTC	Description	Status
B177501	Door warning light / entry light Electrical error	Active/static

5F - Information electronics 1 (2 DTCs)

DTC	Description	Status
B1297F6	Multimedia display unit 1 Wire for video signal, open circuit	Passive/Sporadic
U10BA00	Local data bus No communication	Passive/Sporadic

Technician Notes
2016963030

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.