



Shop Name: Dekra MFC Auction House  
Tel: --  
Email: --  
Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20250325094750  
Test Time: 2025-03-25 09:47:50  
Technician: Sbu

# Volkswagen VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Volkswagen/Golf/--  
VIN: WVWZZZAUZJW306165

Odometer Reading: 163215km  
License Plate: JRR759MP

## Customer Information

Name: Dekra MFC AUCTION HOUSE




















Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V22.00

Serial Number: VB8GJCC01514  
Repair Order Number: --

## System Scanned( 20 )

System	Status/DTC
01 - Engine Control Module 1	 16
02 - Transmission electronics	 0
03 - Brakes 1	 2
08 - Air Conditioning	 1
09 - Electronic central electric	 1
15 - Airbag	 2
16 - Steering column electronics	 0
17 - Instrument cluster	 3
19 - Gateway	 1
20 - High beam assistant	 0
29 - Left light control	 0
39 - Light Control Right	 0
42 - Driver's door electronics	 0
44 - Power Steering	 1
4B - Multi-function module	 0
52 - Passenger's door electronics	 0
5F - Information electronics 1	 5
76 - Parking assistance	 0
D6 - Light Control Left 2	 6



## D7 - Light Control Right 2

 6**DTC ( 44 )****01 - Engine Control Module 1 ( 16 DTCs )**

DTC	Description	Status
P308800	Starter relay Electrical fault in circuit	Passive/Sporadic
P305400	Starter does not turn Mechanically blocked or electrical malfunction	Active/static
U112300	Databus error value received	Passive/Sporadic
U041500	Invalid data received from ABS control unit	Passive/Sporadic
U042800	Steering angle sensor Range/performance	Passive/Sporadic
U101700	ABS brake control module Read out DTC	Passive/Sporadic
U021200	Lost communication with steering column control unit	Passive/Sporadic
P056800	Cruise Control System (CCS) switch Range/performance	Passive/Sporadic
P030000	Random/multiple cylinder Misfire detected	Passive/Sporadic
P030100	Cylinder 1 Misfire detected	Passive/Sporadic
P030300	Cylinder 3 Misfire detected	Passive/Sporadic
P030400	Cylinder 4 Misfire detected	Passive/Sporadic
P030200	Cylinder 2 Misfire detected	Passive/Sporadic
P130A00	Cylinder suppression	Passive/Sporadic
P157000	Engine control unit disabled	Passive/Sporadic
P125000	Fuel level too low	Passive/Sporadic

**03 - Brakes 1 ( 2 DTCs )**

DTC	Description	Status
C10CE29	AUTO HOLD button Range/performance	Passive/Sporadic
C102D00	Tire pressure warning	Passive/Sporadic

**08 - Air Conditioning ( 1 DTC )**

DTC	Description	Status
B10F000	Function restriction caused by compressor shut-off by engine	Passive/Sporadic

**09 - Electronic central electric ( 1 DTC )**

DTC	Description	Status
B133029	Anti-theft alarm system sensor Range/performance	Passive/Sporadic

**15 - Airbag ( 2 DTCs )**

DTC	Description	Status
B12F114	Front passenger airbag indicator Circuit open or short to ground	Passive/Sporadic
B101614	Front passenger airbag off indicator Circuit open or short to ground	Passive/Sporadic

**17 - Instrument cluster ( 3 DTCs )**

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic
B104C29	Key Range/performance	Passive/Sporadic
B1301F0	Transmission control module (TCM) not authorized	Passive/Sporadic

**19 - Gateway ( 1 DTC )**

DTC	Description	Status
U108E00	Control unit in steering wheel No Communication	Passive/Sporadic

**44 - Power Steering ( 1 DTC )**

DTC	Description	Status
U112300	Databus error value received	Passive/Sporadic

**5F - Information electronics 1 ( 5 DTCs )**

DTC	Description	Status
B110007	CD-ROM drive mechanical malfunction	Passive/Sporadic
B106713	Right rear bass speaker Open circuit	Active/static
B106213	Right front bass speaker Open circuit	Active/static
B105F13	Left front bass speaker Open circuit	Active/static

B106513 Left rear bass speaker  
Open circuit

Active/static

### D6 - Light Control Left 2 ( 6 DTCs )

DTC	Description	Status
U140000	Function restriction Caused by low voltage	Passive/Sporadic
C119AF6	Stationary cornering lamp Overtemperature protection active	Passive/Sporadic
C1198F6	Low beam light bulb Overtemperature protection active	Passive/Sporadic
C1199F6	Hi beam light bulb Overtemperature protection active	Passive/Sporadic
C11FD13	Supply for low beam Open circuit	Passive/Sporadic
C119829	Low beam lamp bulb Range/performance	Passive/Sporadic

### D7 - Light Control Right 2 ( 6 DTCs )

DTC	Description	Status
C119AF6	Stationary cornering lamp Overtemperature protection active	Passive/Sporadic
U140000	Function restriction Caused by low voltage	Passive/Sporadic
C1198F6	Low beam light bulb Overtemperature protection active	Passive/Sporadic
C1199F6	Hi beam light bulb Overtemperature protection active	Passive/Sporadic
C11FD13	Supply for low beam Open circuit	Passive/Sporadic
C119829	Low beam lamp bulb Range/performance	Passive/Sporadic

### Technician Notes

2016813824

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.