CONDITION REPORT

Report No:
2017310479
DATE
12/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	12/10/2026		
Inspection Date	12/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	JEEP	Registration Number	FTB508L
Model	WRANGLER UNLIMITED 3.8 SAHARA 4X4 AT [2007-2012]	Register Number	
		Date Of First Licensing	
VIN	1J4BE5H14BL533677	Last COR	
Engine Number		License Expiry Date	31/03/2027
Doors	4	Power / Displacement	
Color	YELLOW	Paint Finish	TWO COAT METALLIC
Year Model	2011	Fuel	PETROL
Km Reading	240,486 KM	Transmission	AUTOMATIC
Cab / Body Type	SUV		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: 1J4BE5H14BL533677

DEKRA

CONDITION REPORT

Report No:
2017310479
DATE
12/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Under bonnet insulation cover Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Right Damaged	Repair
Roof Damaged	Repair
Engine to silencer pipe Welded	Repair
Catalytic converter Welded	Replace
Gearbox Oil Leak	Replace

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	285/65R17	116H	Yokohama	Radial	V	2419	4 mm
Front Right	285/65R17	116H	Yokohama	Radial	V	2419	4 mm
Rear Left	285/65R17	116H	Yokohama	Radial	V	2419	4 mm
Rear Right	285/65R17	116H	Yokohama	Radial	V	2419	4 mm
Spare	285/70R17	118Q	Yokohama	Radial	V	0000	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: 1J4BE5H14BL533677

DEKRA

CONDITION REPORT

Report No:
2017310479
DATE
12/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	MIC/CCN	U0184	LOST COMMUNICATION WITH RADIO	ACTIVE

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: Battery loose.
Electrical Components and Instruments: winch not working. vehicle electronics malfunction.
Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels.
Undercarriage: non-standard exhausted to vehicle.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: 1J4BE5H14BL533677


DEKRA

CONDITION REPORT


Report No:
2017310479
DATE
12/10/2026



Brake test.



Diagnostic.




Diagnostic.



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: 1J4BE5H14BL533677

DEKRA

CONDITION REPORT


Report No:
2017310479
DATE
12/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic.



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: 1J4BE5H14BL533677


DEKRA

CONDITION REPORT


Report No:
2017310479
DATE
12/10/2026




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: 1J4BE5H14BL533677

DEKRA

CONDITION REPORT


Report No:
2017310479
DATE
12/10/2026



VIN PLATE OR STICKER




ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Water level


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: 1J4BE5H14BL533677

DEKRA

CONDITION REPORT

Report No:
2017310479
DATE
12/10/2026



Front Bumper



Front Bumper



Under bonnet insulation cover



Bonnet



Roof



Catalytic converter

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: 1J4BE5H14BL533677


DEKRA

CONDITION REPORT

Report No:
2017310479
DATE
12/10/2026



Catalytic converter



Engine to silencer pipe



Engine to silencer pipe



Engine



Gearbox



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: 1J4BE5H14BL533677