DEKRA

CONDITION REPORT

Report No:
2017309295
DATE
08/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	08/10/2026		
Inspection Date	08/10/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC
Manufacturer	GWM	Registration Number	MX90SZGP
Model	P-SERIES P300 2.4T LT 4X4 DSL D-CAB PU AT [2025-ON]	Register Number	
		Date Of First Licensing	
VIN	AAPV0292620712702	Last COR	
Engine Number		License Expiry Date	
Doors	4	Power / Displacement	
Color	WHITE	Paint Finish	TWO COAT UNI
Year Model	2025	Fuel	DIESEL
Km Reading	154,171 KM	Transmission	AUTOMATIC
Cab / Body Type	DOUBLE CAB		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAPV0292620712702

DEKRA

CONDITION REPORT

Report No: 2017309295
DATE 08/10/2026



Damage	Repair Way
Indicator Light Front Right Damaged	Replace
Tail Light Left Scratched	Replace
Seat Front Right Damaged	Repair
Front Bumper Paintwork • Scratched	Replace
Bonnet Residual Traces of Repair	Repair
Front Fender Left Dented	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Left Paintwork • Chipmarks	Repair
Door Front Right Dented	Repair
Door Rear Left Paintwork • Chipmarks	Repair
Door Rear Right Residual Traces of Repair	Repair
Tailgate Dented	Repair
Rocker Panel Left Paintwork • Scratched	Repair
Rocker Panel Right Paintwork • Scratched	Repair
Windscreen Chipped	Repair
Rim Front Left Defective	Repair
Chassis Damaged	Repair
Gearbox Oil Sweat	Repair
Jack Missing	Replace
Triangle Missing	Replace
Warning lights illuminated on dashboard	Repair
Tonneau cover damaged	Repair
Front right shock absorber weak	Replace
VEHICLE HAS SAPS VIN NUMBER.	REPAIR

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/60 R18	110H	Goodyear	Wrangler	V	1423	5 mm
Front Right	265/60 R18	110H	Goodyear	Wrangler	V	3222	4 mm
Rear Left	265/60 R18	110H	Goodyear	Wrangler	V	4122	7 mm
Rear Right	265/60 R18	110H	Goodyear	Wrangler	V	1124	6 mm
Spare	265/60 R18	110H	Cooper	Discoverer	V	0000	6 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAPV0292620712702

DEKRA

CONDITION REPORT

Report No:
2017309295
DATE
08/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	A/T(AUTOMATIC TRANSMISSION)	P278798	CLUTCH OVERHEATED(LEVEL1)	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE EXTERIOR, INTERIOR, ELECTRICAL, AND MECHANICAL PARTS.Interior: Vehicle interior dirty and panels scratched.
Body • Exterior: Poor residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.
Undercarriage: Bottom of engine covered.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAPV0292620712702

DEKRA

CONDITION REPORT

Report No:
2017309295
DATE
08/10/2026



LICENSE DISC



VIN PLATE OR STICKER



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAPV0292620712702

DEKRA

CONDITION REPORT

Report No:
2017309295
DATE
08/10/2026



90 DEGREE REAR



90 DEGREE RIGHT



LR TYRE TREAD



LF TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAPV0292620712702


DEKRA

CONDITION REPORT

Report No:
2017309295
DATE
08/10/2026



Front chassis



Rear chassis



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic Transmission

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAPV0292620712702

DEKRA

CONDITION REPORT

Report No:
2017309295
DATE
08/10/2026



ENGINE 1




Oil cap and dipstick




Spare wheel Accessories



Spare wheel



Shock absorber report



Diagnostic report page 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAPV0292620712702

DEKRA

CONDITION REPORT


Report No:
2017309295
DATE
08/10/2026



Diagnostic report page 2



Diagnostic report page 3



Diagnostic report page 4



Tonneau cover



Seat Front Right



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAPV0292620712702

DEKRA

CONDITION REPORT

Report No:
2017309295
DATE
08/10/2026



Front Fender Right



Door Front Right



Door Rear Right



Rear Fender Right



Tail Light Left



Tailgate

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAPV0292620712702


DEKRA

CONDITION REPORT

Report No:
2017309295
DATE
08/10/2026




Rear Fender Left



Door Rear Left



Door Rear Left



Door Front Left



Door Front Left



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAPV0292620712702

DEKRA

CONDITION REPORT


Report No:
2017309295
DATE
08/10/2026



Bonnet



Front Bumper



Front Bumper



Windscreen



Water level



Rim Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAPV0292620712702

DEKRA

CONDITION REPORT

Report No:
2017309295
DATE
08/10/2026



Rocker Panel Left



Gearbox



Chassis



Rocker Panel Right



Rocker Panel Right



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAPV0292620712702

DEKRA

CONDITION REPORT

Report No:
2017309295
DATE
08/10/2026



Indicator Light Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAPV0292620712702