DEKRA

CONDITION REPORT

Report No:
2017312798
DATE
15/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	15/10/2026		
Inspection Date	15/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	LL98LGGP
Model	POLO VIVO 1.4 55KW TRENDLINE 5-DR [2023-2024]	Register Number	
		Date Of First Licensing	
VIN	AAVZZZ6R1RU006232	Last COR	
Engine Number		License Expiry Date	
Doors	5	Power / Displacement	
Color	GREY	Paint Finish	M - METALLIC
Year Model	2023	Fuel	PETROL
Km Reading	136,317 KM	Transmission	MANUAL
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6R1RU006232

DEKRA

CONDITION REPORT

Report No:
2017312798
DATE
15/10/2026



Damage	Repair Way
Switch Electrical Window Winder front left Damaged	Replace
Switch Electrical Window Winder front right Damaged	Replace
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Right Dented	Repair
Door Rear Left Paintwork • Discoloured	Repair
Door Rear Right Paintwork • Chipmarks	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Chipped	Repair
Tyre Front Right Smooth	Replace
Tyre Rear Right Smooth	Replace
No license disc	Replace
Right and left tires deferred name brand	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.5	2.5	-	
Rear	1.5	1.4	-	
Emergency / Parking	0.7	0.8	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R15	88H	Win run	R330	V	2224	1 mm
Front Right	185/65R15	88H	Nexen	N blue	V	5020	0 mm
Rear Left	185/65R15	88H	Win run	R330	V	2124	2 mm
Rear Right	185/65R15	88H	Nexen	N blue	V	5020	0 mm
Spare	185/60R14	82H	Goodyear	Efficient gr	V	0000	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6R1RU006232

DEKRA

CONDITION REPORT

Report No:
2017312798
DATE
15/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	PASSIVE SPORADIC	U112100	DATABUS MESSAGE MISSING	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6R1RU006232

DEKRA

CONDITION REPORT


Report No:
2017312798
DATE
15/10/2026



Shock and brake report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6R1RU006232

DEKRA

CONDITION REPORT

Report No:
2017312798
DATE
15/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6R1RU006232

DEKRA

CONDITION REPORT

Report No:
2017312798
DATE
15/10/2026



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6R1RU006232


DEKRA

CONDITION REPORT

Report No:
2017312798
DATE
15/10/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Expention bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6R1RU006232

DEKRA

CONDITION REPORT

Report No:
2017312798
DATE
15/10/2026



Oil cap and dipstick




Water level



Switch Electrical Window Winder front left



Switch Electrical Window Winder front right



Rear Fender Right



Door Rear Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6R1RU006232

DEKRA

CONDITION REPORT

Report No:
2017312798
DATE
15/10/2026



Front Fender Right



Front Bumper




Bonnet



Door Rear Left



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6R1RU006232

DEKRA

CONDITION REPORT

Report No:
2017312798
DATE
15/10/2026



Tyre Rear Right



Tyre Front Right



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6R1RU006232