DEKRA

CONDITION REPORT

Report No:
2017317553
DATE
26/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	26/10/2026		
Inspection Date	26/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	VOLKSWAGEN	Registration Number	LV34THGP
Model	POLO VIVO 1.4 55KW TRENDLINE 5-DR [2023-2024]	Register Number	
		Date Of First Licensing	
VIN	AAVZZZ6RXRU015818	Last COR	
Engine Number		License Expiry Date	31/05/2026
Doors	5	Power / Displacement	
Color	WHITE	Paint Finish	C - COMMON
Year Model	2024	Fuel	PETROL
Km Reading	52,546 KM	Transmission	MANUAL
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RXRU015818

DEKRA

CONDITION REPORT

Report No:
2017317553
DATE
26/10/2026



Damage	Repair Way
Side Mirror Right Damaged	Repair
Front Bumper Paintwork • Scratched	Repair
Front Fender Left Paintwork • Scratched	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Rear Left Dented	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Sill Panel Right Dented	Repair
Radiator Cradle Damaged	Repair
R/R tire deferred size	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.7	2.7	-	
Rear	1.4	1.5	-	
Emergency / Parking	1	1	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/60R14	82H	Goodyear	Efficient gr	V	1424	3 mm
Front Right	185/60R14	82H	Goodyear	Efficient gr	V	1424	3 mm
Rear Left	185/60R14	82H	Goodyear	Efficient gr	V	1424	3 mm
Rear Right	165/65R14	79H	Nexen	Cp661	V	3619	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RXRU015818

DEKRA

CONDITION REPORT

Report No:
2017317553
DATE
26/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	PASSIVE SPORADIC	U010000	LOST COMMUNICATION WITH ECM/PCM	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RXRU015818

DEKRA

CONDITION REPORT


Report No:
2017317553
DATE
26/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE REAR



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RXRU015818

DEKRA

CONDITION REPORT

Report No:
2017317553
DATE
26/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual




DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RXRU015818

DEKRA

CONDITION REPORT


Report No:
2017317553
DATE
26/10/2026



ENGINE 1



CHASSIS



ENGINE 2



Expention bottle



Oil cap and dipstick



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RXRU015818

DEKRA

CONDITION REPORT

Report No:
2017317553
DATE
26/10/2026



RF TYRE TREAD




LF TYRE TREAD




LR TYRE TREAD



No spare wheel



Shock and brake report



Diagnostic report


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RXRU015818

DEKRA

CONDITION REPORT

Report No:
2017317553
DATE
26/10/2026



Diagnostic report



Water level




Rear Fender Right



Door Rear Right



Side Mirror Right



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RXRU015818

DEKRA

CONDITION REPORT

Report No:
2017317553
DATE
26/10/2026




Front Bumper




Front Fender Left



Door Front Left



Door Rear Left



Rear Fender Left



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RXRU015818

DEKRA

CONDITION REPORT

Report No:
2017317553
DATE
26/10/2026



Rear bumper



Boot Lid / Hatch door



Sill Panel Right



Radiator Cradle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RXRU015818