DEKRA

CONDITION REPORT

Report No:
2017315732
DATE
22/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	22/10/2026		
Inspection Date	22/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	VOLKSWAGEN	Registration Number	JZV499NW
Model	POLO 1.6 TRENDLINE 5-DR [2009-2015]	Register Number	
VIN	AAVZZZ6RZEU031299	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	GREY	Power / Displacement	
Year Model	2014	Paint Finish	TWO COAT UNI
Km Reading	150,201 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZEU031299

DEKRA

CONDITION REPORT

Report No:
2017315732
DATE
22/10/2026





Damage	Repair Way
Engine Wiring Defective	Repair
Bonnet safety caps Defective	Replace
Under bonnet insulation cover Damaged	Repair
Air Conditioner Insufficient	Replace
Headlight Left Damaged	Replace
Seat Front Left Damaged	Repair
Hood Lining Damaged	Replace
Door Panel Rear Left Torn / Cut	Repair
Side Mirror Left Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Bonnet Residual Traces of Repair	Repair
A • Pillar Right Damaged	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Paintwork • Scratched	Repair
Rear Fender Left / Inner Tray Damaged	Repair
Door Front Left Dented	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Sill Panel Left Damaged	Repair
Sill Panel Right Damaged	Repair
Roof Residual Traces of Repair	Repair
Windscreen Cracked	Replace
Stabilizer Mounting Front Left Damaged	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Tyre Front Left Damaged	Replace
Tyre Front Right Worn	Replace
Tyre Rear Left Damaged	Replace
Tyre Rear Right Damaged	Replace
Sub Frame Damaged	Replace
Engine to silencer pipe Damaged	Repair
Belly plates Damaged	Replace
Radiator Cradle Damaged	Replace
Steering Shudder	Repair
Engine Noise Excessive	Repair
Bottom steering column cover damaged	Replace
Deceleration parking brake defective	Repair
Aircon condenser dented	Repair
Center exhaust cross member bracket damaged	Repair
Rear left tyre regrooved	Replace
Front left and right tyre sizes different	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZEU031299

DEKRA

CONDITION REPORT

Report No:
2017315732
DATE
22/10/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.75	2.82	-	
Rear	1.3	1.51	-	
Emergency / Parking	0.67	0.76	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/60 R14	82H	Tracmax	X-privilo	V	1922	0 mm
Front Right	175/65 R14	82T	Dunlop	Sp-Sport	V	1912	0 mm
Rear Left	185/60 R14	82H	Campiro	GT Radial	V	3520	0 mm
Rear Right	185/60 R14	82H	Continental	ContiEco	V	0219	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	01-ENGINE CONTROL MODULE 1	17978:000	ENGINE CONTROL UNIT DISABLED	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: Engine Compartment: Rust inside expansion bottle.
Interior: Vehicle interior dirty and panels scratched.
Body • Exterior: Poor residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.Boot does not open.
Axle and Suspension: Front suspension faulty.Signs of vehicle grabbing.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZEU031299

DEKRA

CONDITION REPORT

Report No: 2017315732
DATE 22/10/2026

strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZEU031299

DEKRA

CONDITION REPORT

Report No:
2017315732
DATE
22/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE LEFT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZEU031299

DEKRA

CONDITION REPORT

Report No:
2017315732
DATE
22/10/2026




ODOMETER




DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



Manual Transmission



RF TYRE TREAD



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZEU031299


DEKRA

CONDITION REPORT


Report No:
2017315732
DATE
22/10/2026



LR TYRE TREAD



RR TYRE TREAD



Front chassis



Rear chassis



Aircon condenser



Center exhaust cross member br

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZEU031299

DEKRA

CONDITION REPORT

Report No:
2017315732
DATE
22/10/2026



Oil cap and dipstick



Bottom steering column cover




ENGINE 1



VIN PLATE OR STICKER



LICENSE DISC



SHOCK AND BRAKE REPORT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZEU031299


DEKRA

CONDITION REPORT

Report No:
2017315732
DATE
22/10/2026



DIAGNOSTIC REPORT PAGE 1



DIAGNOSTIC REPORT PAGE 2



Windscreen



Front Fender Left



Side Mirror Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZEU031299

DEKRA

CONDITION REPORT

Report No:
2017315732
DATE
22/10/2026



Rear Fender Left



Door Rear Left



Door Rear Left



Seat Front Left



Seat Front Left



Hood Lining

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZEU031299

DEKRA

CONDITION REPORT

Report No:
2017315732
DATE
22/10/2026



Door Panel Rear Left



Rear bumper



Rear bumper



Rear bumper



Rear Fender Right



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZEU031299

DEKRA

CONDITION REPORT


Report No:
2017315732
DATE
22/10/2026



Door Rear Right



Door Rear Right




A • Pillar Right



A • Pillar Right



Roof



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZEU031299

DEKRA

CONDITION REPORT

Report No:
2017315732
DATE
22/10/2026



Door Front Right



Air Conditioner



Bonnet



Bonnet safety caps



Bonnet safety caps



Under bonnet insulation cover

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZEU031299

DEKRA

CONDITION REPORT

Report No:
2017315732
DATE
22/10/2026



Headlight Left



Control Arm Bush(es) Front Axle Right



Control Arm Bush(es) Front Axle Left



Front Bumper



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZEU031299


DEKRA

CONDITION REPORT

Report No:
2017315732
DATE
22/10/2026



Sill Panel Left



Rear Fender Left / Inner Tray



Sill Panel Right



Sub Frame



Sub Frame



Belly plates

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZEU031299


DEKRA

CONDITION REPORT

Report No:
2017315732
DATE
22/10/2026



Belly plates



Tyre Front Right



Tyre Front Left



Stabilizer Mounting Front Left



Engine Wiring



Radiator Cradle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZEU031299

DEKRA

CONDITION REPORT

Report No:
2017315732
DATE
22/10/2026




Radiator Cradle



Engine to silencer pipe



Tyre Rear Right



Tyre Rear Left



Inner Boot Floor Pan and Spare Wheel Well



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZEU031299