DEKRA

CONDITION REPORT

Report No:
2017326886
DATE
18/11/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	18/11/2026		
Inspection Date	18/11/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	VOLKSWAGEN	Registration Number	KX87FSGP
Model	POLO VIVO 1.4 55KW TRENDLINE 5-DR [2021-2023]	Register Number	
		Date Of First Licensing	
VIN	AAVZZZ6RZNU018826	Last COR	
Engine Number		License Expiry Date	31/03/2027
Doors	5	Power / Displacement	
Color	BLUE	Paint Finish	TWO COAT METALLIC
Year Model	2022	Fuel	PETROL
Km Reading	230,090 KM	Transmission	MANUAL
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU018826

DEKRA

CONDITION REPORT

Report No:
2017326886
DATE
18/11/2026





Damage	Repair Way
Engine Management Lights Set	Repair
Parcel Tray Missing	Replace
Front Bumper Damaged	Repair
Grill Damaged	Repair
Bonnet Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Fuel Flap Damaged	
Windscreen Damaged	Replace
Control Arm Bush(es) Front Axle Left Worn	Replace
Control Arm Bush(es) Front Axle Right Worn	Replace
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Tyre Rear Left Worn	Replace
Tyre Rear Right Worn	Replace
Spare Tyre Defective	Replace
Radiator Cradle Damaged	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.65	2.73	-	
Rear	1.49	1.32	-	
Emergency / Parking	1.35	0.92	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/60R15	84H	Continental	Contipremiu	V	3619	0 mm
Front Right	185/60R15	84H	Sumitomo	Radial	V	1724	0 mm
Rear Left	185/60R15	84H	Sumitomo	Radial	V	2524	0 mm
Rear Right	185/60R15	84H	Sumitomo	Radial	V	2524	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU018826

DEKRA

CONDITION REPORT

Report No:
2017326886
DATE
18/11/2026

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels. Repair work done to vehicle below standard.
Tyres and Rims: spare wheel missing.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU018826

DEKRA

CONDITION REPORT

Report No:
2017326886
DATE
18/11/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual.



FRONT RIGHT CORNER



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU018826

DEKRA

CONDITION REPORT

Report No:
2017326886
DATE
18/11/2026



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR



90 DEGREE RIGHT



Oil cap and dipstick.



ENGINE 1


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU018826


DEKRA

CONDITION REPORT

Report No:
2017326886
DATE
18/11/2026



Undercarriage front.




Undercarriage rear.




RF TYRE TREAD



RR TYRE TREAD



LR TYRE TREAD



LF TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU018826


DEKRA

CONDITION REPORT


Report No:
2017326886
DATE
18/11/2026



Brake test.



Diagnostic.



Diagnostic.



LICENSE DISC



VIN PLATE OR STICKER



Water level


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU018826

DEKRA

CONDITION REPORT

Report No:
2017326886
DATE
18/11/2026



Front Bumper



Front Bumper



Grill



Bonnet



Door Rear Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU018826

DEKRA


CONDITION REPORT

Report No:
2017326886
DATE
18/11/2026


Rear bumper


Rear bumper


Boot Lid / Hatch door


Door Rear Right


Door Front Right


Front Fender Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU018826

DEKRA

CONDITION REPORT

Report No:
2017326886
DATE
18/11/2026



Rear Fender Right



Fuel Flap



Engine Management Lights



Windscreen



Parcel Tray



Spare Tyre

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU018826

DEKRA

CONDITION REPORT


Report No:
2017326886
DATE
18/11/2026



Tyre Rear Left



Tyre Rear Right



Tyre Front Left



Tyre Front Right



Radiator Cradle



Control Arm Bush(es) Front Axle Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU018826

DEKRA

CONDITION REPORT

Report No:
2017326886
DATE
18/11/2026



Control Arm Bush(es) Front Axle Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU018826